INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/10/15	MAKE	KOBELCO	MODEL	7035
SERIAL No.	PLATE : GL-00260		STAMP	00260	
HR METER	4244 HR	SHOE	760FLAT	YEAR	YR

ENGINE : MODEL S/N		
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
OPERATION PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	サブタンク割れあり SUB TANK: MUCH CRACKED
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
Computer	(OK)・ NG	
Swing	FAIR ・(Attn)	*2
Travel	(FAIR)・ Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 9m×1, 6m×3, 3m×1	
BOOM TOTAL	39m	
TOP SHEAVE	(YES)・ NO	
JIB	12m	
TOP, BOTTOM, 3m×2		
TOWER		

INTERIOR See Photos. 写真参照		
INTERIOR COND.	(CLEAN)・ FAIR ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	破れあり CUTS
Glasses	(FAIR)・ Attn	
AirCon	A/C ・(H/C)・ H only ・ C only ・ None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
WEIGHT	2	
HOOK	35t, SWIVEL HOOK	
FREE FALL	(YES) ・ NO	
LIFTER	YES ・(NO)	
COMMENT		
ブームジョイントピン4本欠 4 BOOM JOINT PINS: MISSING		
ペンダントジョイントピン2本欠 2 PENDANT JOINT PINS: MISSING		
*1 E/G上部にじみあり UPPER PART OF ENGINE: OIL OOZING		
*2 旋回ロックピン不良 SWING LOCK PIN: MALFUNCTION		
@NARITA YARD		
BOOM: TOP, BOTTOM		
@SAKURA YARD		
BOOM: 9m×1, 6m×3, 3m×1, SWIVEL HOOK		
JIB: TOP, BOTTOM, 3m×2		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。