

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2026/10/9	MAKE	KOMATSU	MODEL	FD120-8		
SERIAL	7276			STAMP	M246-7276		
HR METER	8536	HR	Odometer	6974	km	YEAR	YR
CAB/CNP	CAB	/	CNP	/	NONE	TIRE SIZE	10.00R20
MAX LIFTING HEIGHT	3.0	m	VIEW	MONO	FORK LENGTH	2200	mm
FORK SPEC	サイドシフト SIDE-SHIFT						

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
TRANSMISSION & TRAVEL		
T/M TYPE	PS	DD
Transmission	FAIR	Attn
Travel	FAIR	Attn
FOOT BRAKE	FAIR	Attn *1
PARKING BRAKE	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR	Attn 破れあり TORN
Glasses	FAIR	Attn
AirCon	A/C · H/C · H only · C only · None	
HYDRAULICS		
MAST Cylinder	FAIR	Attn
TILT Cylinder	FAIR	Attn
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR	
COMMENT		
右ステアリングシリンダーにじみあり		
RIGHT STEERING CYLINDER: OIL OOZING		
サイドシフトシリンダー油漏れ小 SIDE-SHIFT CYLINDER: OIL LEAKING		
*1 ペダルを踏んだらブザーが鳴り1秒後くらいにブレーキが効く		
*1 WARNING SOUNDS WHEN STEPPING ON THE PEDAL,		
& WORKING THE BRAKE ABOUT A SECOND LATER		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		
3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。