

INSPECTION SHEET 検品書  
WHEEL LOADER タイヤショベル

|                 |                                        |      |          |           |                            |
|-----------------|----------------------------------------|------|----------|-----------|----------------------------|
| INSPECTION DATE | 2026/9/30                              | MAKE | TCM      | MODEL     | L13-3                      |
| SERIAL          | RYU4F000V00007077                      |      |          | STAMP     | S50-07077                  |
| HR METER        | 5144                                   | HR   | Odometer | -         | km                         |
|                 |                                        |      |          | YEAR      | 2007 YR                    |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |          | TIRE SIZE | 16.9-24 10PR (SNOW, SPIKE) |

|                                       |                                                                                   |
|---------------------------------------|-----------------------------------------------------------------------------------|
| <b>ENGINE : MODEL</b> 4BG1 <b>S/N</b> |                                                                                   |
| Oil leakage                           | FAIR · <input checked="" type="radio"/> Attn E/G周りにじみあり AROUND ENGINE: OIL OOZING |
| Blow-By                               | FAIR · Attn A LITTLE · MIDDLE · SEVERE                                            |
| Sound                                 | <input checked="" type="radio"/> Attn                                             |
| Oil                                   | <input checked="" type="radio"/> Attn                                             |
| Exhaust Color                         | <input checked="" type="radio"/> Attn                                             |
| US EPA                                | <input checked="" type="radio"/> YES · NO                                         |
| <b>OPERATION PUMP</b>                 |                                                                                   |
| Sound                                 | <input checked="" type="radio"/> Attn                                             |
| Oil leakage                           | <input checked="" type="radio"/> Attn                                             |
| Power                                 | <input checked="" type="radio"/> Attn                                             |
| <b>COOLING SYSTEM</b>                 |                                                                                   |
| Radiator                              | <input checked="" type="radio"/> Attn                                             |
| Oil Cooler                            | <input checked="" type="radio"/> Attn                                             |
| <b>TRANSMISSION &amp; TRAVEL</b>      |                                                                                   |
| T/M TYPE                              | <input checked="" type="radio"/> PS · DD                                          |
| Transmission                          | <input checked="" type="radio"/> Attn                                             |
| Travel                                | <input checked="" type="radio"/> Attn                                             |
| FOOT BRAKE                            | <input checked="" type="radio"/> Attn                                             |
| PARKING BRAKE                         | <input checked="" type="radio"/> Attn                                             |
| <b>INTERIOR See Photos. 写真参照</b>      |                                                                                   |
| INTERIOR COND.                        | CLEAN · <input checked="" type="radio"/> FAIR · DIRTY                             |
| Operator's Seat                       | FAIR · <input checked="" type="radio"/> Attn 破れあり MUCH WORN                       |
| Glasses                               | <input checked="" type="radio"/> Attn                                             |
| AirCon                                | A/C · H/C · <input checked="" type="radio"/> H only · C only · None               |
| <b>FRONT &amp; CYLINDERS</b>          |                                                                                   |
| Arm                                   | FAIR · <input checked="" type="radio"/> Attn *1                                   |
| Bell crank                            | <input checked="" type="radio"/> Attn                                             |
| Bucket                                | FAIR · <input checked="" type="radio"/> Attn シリンダーにじみあり CYLINDER: OIL OOZING      |
| Articulate                            | <input checked="" type="radio"/> Attn                                             |

|                                                                                                                                               |                                                                                                     |
|-----------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                                                                                                       |                                                                                                     |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)                                                                                  | 3                                                                                                   |
| TIRE WEAR                                                                                                                                     | <input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR                                          |
| <b>COMMENT</b>                                                                                                                                |                                                                                                     |
| STEERING TYPE <input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING |                                                                                                     |
| RIDE CONTROL                                                                                                                                  | YES · <input checked="" type="radio"/> NO                                                           |
| <b>ATTACHMENTS</b>                                                                                                                            |                                                                                                     |
| STD BKT                                                                                                                                       | <input checked="" type="radio"/> YES · OTHER                                                        |
| BLADE                                                                                                                                         | YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO |
| <b>COMMENT</b>                                                                                                                                |                                                                                                     |
| スピードメーター不良 SPEED METER: MALFUNCTION                                                                                                           |                                                                                                     |
| *1 右シリンダー油漏れあり RIGHT CYLINDER: OIL LEAKING                                                                                                    |                                                                                                     |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)                                                                          |                                                                                                     |
| 3                                                                                                                                             |                                                                                                     |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。