# INSPECTION SHEET 検品書
## ROLLER ローラー

| | | | | | |
|---|---|---|---|---|---|
| INSPECTION DATE | 2026/10/5 | MAKE | KAWASAKI | MODEL | K20 Ⅱ |
| SERIAL | KR20D-2251 | | | STAMP | KR20D-2251 |
| HR METER | 243 HR | Odometer | – km | YEAR | YR |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / (CNP) / NONE | | | TIRE SIZE | 9.00-20 |

| ENGINE : MODEL | | S/N |
|---|---|---|
| Oil leakage | (FAIR) · Attn | |
| Blow-By | (FAIR) · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | (FAIR) · Attn | |
| Oil | (FAIR) · Attn | |
| Exhaust Color | (FAIR) · Attn | |
| US EPA | YES · (NO) | |
| **OPERATION PUMP** | | |
| Sound | (FAIR) · Attn | |
| Oil leakage | (FAIR) · Attn | |
| Power | (FAIR) · Attn | |
| **COOLING SYSTEM** | | |
| Radiator | (FAIR) · Attn | |
| Oil Cooler | (FAIR) · Attn | |
| **TRANSMISSION & TRAVEL** | | |
| T/M TYPE | PS · (DD) | |
| Transmission | (FAIR) · Attn | |
| Travel | (FAIR) · Attn | |
| FOOT BRAKE | (FAIR) · Attn | |
| PARKING BRAKE | (FAIR) · Attn | |
| **INTERIOR** | See Photos. 写真参照 | |
| INTERIOR COND. | CLEAN · (FAIR) · DIRTY | |
| Operator's Seat | (FAIR) · Attn | |
| Glasses | FAIR · Attn | |
| AirCon | A/C · H/C · H only · C only · (None) | |
| **OTHERS** | | |
| Vibratory | FAIR · Attn | |
| Watering | FAIR · (Attn) | *1 |
| Articulate | FAIR · Attn | |

**UNDERCARRIAGE :** See Photos. 写真参照

| | |
|---|---|
| **RUST**(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
| TIRE WEAR (FAIR) · WORN · UNEVEN WEAR | |

**COMMENT**

ステアリングシリンダー油漏れ、メッキ剥がれあり

STEERING CYLINDER: OIL LEAKING, COATING PEELED

*1 タイヤ散水フィルタードレーン破損あり、タイヤ散水不良(路面散水OK)

*1 WATERING FILTER DRAIN FOR SPRINKLING TO TIRES: BROKEN, MALFUNCTION TO SPRINKLE TO TIRES (SPRINKLING TO ROAD: OK)

| | |
|---|---|
| **RUST of BODY**(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。