INSPECTION SHEET 検品書

ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/11/4	MAKE	KATO	MODEL	KRM-13HM
SERIAL No.	PLATE : 5912262		STAMP : KR130-2262		
HR METER	15580 HR		Odometer	105365 km	
TIRE SIZE	275/80R22.5		YEAR	2007 YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR・(Attn)	E/G上部油漏れあり UPPER PART: OIL LEAKING
Blow-By	(FAIR)・Attn	A LITTLE・MIDDLE・SEVERE
Sound	(FAIR)・Attn	
Oil	(FAIR)・Attn	
Exhaust Color	FAIR・(Attn)	白煙あり WHITE FUMES
OPERATION PUMP		
Sound	(FAIR)・Attn	
Oil leakage	(FAIR)・Attn	
Power	(FAIR)・Attn	
COOLING SYSTEM		
Radiator	(FAIR)・Attn	
Oil Cooler	(FAIR)・Attn	
OPERATING SYSTEM		
Computer	(OK)・NG	*1
Swing	(FAIR)・Attn	
Travel	(FAIR)・Attn	
TRANSMISSION		
Transmission	(FAIR)・Attn	
No. OF GEARS	3 GEARS	
4WD	(4WD)・6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・(FAIR)・DIRTY	
Operator's Seat	(FAIR)・Attn	
Glasses	(FAIR)・Attn	
AirCon	(A/C)・H/C・H only・C only・None	

COMMENT

A/C効かない A/C: MALFUNCTION

BOOM		
No. of Section	6 SECTIONS	
CRACK/ENFORCEMENT	(FAIR)・Attn	
DERRICKING CYL.	(FAIR)・Attn	
EXTENSION CYL.	(FAIR)・Attn	
JIB	(YES)・NO	
JIB TYPE	STD・(PWR)	
MAIN & SUB WIRE	(YES)・NO	
FREE FALL	YES・(NO)	
HOOK	4.9t, BALL	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR・(WORN)・UNEVEN WEAR

COMMENT

OUTRIGGERS

OUTRIGGERS	X・(H) *2			
OUTRIGGERS COND.	(FAIR)・Attn			
Oil leakage (JACK CYL.)	FRONT	L・R	REAR	L・R
Oil leakage (SLIDE CYL.)	FRONT	L・R	REAR	L・R

COMMENT

ロータリー油漏れあり ROTARY: OIL LEAKING

*1 コンピュータ解除で操作可

*1 NEED TO CUT THE COMPUTER TO OPERATE

*2 アウトリガーストロークセンサー左右F不良

*2 FRONT OUTRIGGER EXTENSION SENSORS: MALFUNCTION

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。