INSPECTION SHEET 検品書

CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/10/22	MAKE	MOROOKA	MODEL	MST-1500
SERIAL	15466			STAMP	15466
HR METER	3846 HR	Odometer	km	YEAR	1990 YR
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE			SHOE	700R
TIRE					

ENGINE : MODEL	S/N	
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	No. OF GEARS — GEARS
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
Swing	FAIR · Attn	
Articulate	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	(FAIR) · Attn	
INTERIOR	See Photos. 写真参照	
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	FAIR · (Attn)	ドア1枚欠 SOME DOOR GLASS: MISSING
AirCon	A/C · H/C · (H only) · C only · None	

MAIN FRAME		
MAIN FLAME	(FAIR) · Attn	
VESSEL		
VESSEL	FAIR · (Attn)	*1
REAR GATE TYPE	(NORMAL) · L-GATE (FLAT)	
REAR GATE	FAIR · (Attn)	*2
UNDERCARRIAGE:	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR	

COMMENT

リペイントあり REPAINTED

ヒーター風出ない HEATER: NOT BLOWING AIR

*1 左側リフトシリンダーにじみ、右側油漏れ小

*1 LEFT LIFT CYLINDER: OIL OOZING, RIGHT ONE: OIL LEAKING

*2 外れあり(ベッセル内にあり)、取付ピン欠

*2 COME OFF (PUTTING ON VESSEL), PINS: MISSING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。