INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/10/22	MAKE	CAT	MODEL	301.5CR
SERIAL	CAT03015HRAA02061		STAMP	CAT03015HRAA02061	
HR METER	3554 HR		YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / (NONE)		SHOE	230R	

ENGINE : MODEL S/N		
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
Swing	(FAIR)・ Attn	
Travel	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・(None)	
BOOM / ARM / BKT		
Boom	(FAIR)・ Attn	
Boom Cylinder	FAIR ・(Attn)	サビあり RUSTY
Arm	(FAIR)・ Attn	
Arm Cylinder	(FAIR)・ Attn	
ATTACHMENT	(FAIR)・ Attn	
BKT Cylinder	(FAIR)・ Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		
COMMENT			
左右走行モーター油漏れあり TRAVEL MOTORS: OIL LEAKING			
クローラー伸縮:油圧掛かるが動作しない			
EXPANDABLE CYLINDERS: NOT MOVING			
(ABLE TO SUPPLY SOME HYDRAULIC PRESSURE)			
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )		
Lever	LONG ・ (WRIST)		
Multi	MULTI ・ 2 ・(NO)		
ARM-CRANE	YES ・(NO)		
BLADE	(YES)・ NO		
OFFSET	YES ・(NO)		
OFFSET Cylinder	FAIR ・ Attn		
Piping	YES ・(NO)	Breaker only ・ Multi	
COMMENT			
スイングガタあり SWING PART: LOOSE			
*1 オイルパン周りにじみあり AROUND OIL PAN: OIL OOZING			
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。