INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/10/21	MAKE	CAT	MODEL	E110B
SERIAL	9HF03203		STAMP	9HF03203	
HR METER	E5507 HR		YEAR	YR	
CAB/CNP	ROPS CAB (/ CAB /) ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL S/N		
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
Swing	(FAIR)・ Attn	
Travel	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	穴、破れあり HOLE, CUTS
Glasses	(FAIR)・ Attn	
AirCon	A/C ・ (H/C) ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	(FAIR)・ Attn	
Boom Cylinder	(FAIR)・ Attn	
Arm	(FAIR)・ Attn	ガタあり LOOSE
Arm Cylinder	FAIR ・(Attn)	油漏れ小 OIL LEAKING
ATTACHMENT	(FAIR)・ Attn	ガタあり LOOSE
BKT Cylinder	FAIR ・(Attn)	油漏れあり OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		
COMMENT			
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )		
Lever	LONG ・ (WRIST)		
Multi	MULTI ・ 2 ・ (NO)		
ARM-CRANE	YES ・(NO)		
BLADE	YES ・(NO)		
OFFSET	YES ・(NO)		
OFFSET Cylinder	FAIR ・ Attn		
Piping	YES ・(NO)	Breaker only ・ Multi	

COMMENT

全体的にホースひび割れ多い MANY HOSES: CRACKED

HRメーターストップ HR METER: STOPPED

*1 ヘッド周り、オイルフィルターにじみあり

*1 AROUND CYLINDER HEAD & OIL FILTER: OIL OOZING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。