INSPECTION SHEET 検品書

GENERATOR / COMPRESSOR / WELDER 発電機･コンプレッサー･ウェルダー

INSPECTION DATE	2026/10/19	CATEGORY	(GENERATOR) / COMPRESSOR / WELDER
MAKE	DENYO	MODEL	DCA-220SPM
SERIAL	1335613	STAMP	NOT FOUND
HR METER	7095 HR	TIRE SIZE	YEAR YR

ENGINE :	MODEL	MITSUBISHI S6B	S/N	28432
Oil leakage	FAIR ・(Attn)	*1	Oil	(FAIR) ・ Attn
Blow-By	(FAIR) ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE	Exhaust Color	(FAIR) ・ Attn
Sound	(FAIR) ・ Attn		Radiator	(FAIR) ・ Attn

GENERATOR					
RATED POWER	195 / 220	KVA	Leaking Breaker Condition	(FAIR) ・ Attn	
RATED AMPERE	563, 281 / 577, 289	A	Insulation Condition	(FAIR) ・ Attn	
Output Terminal	(FAIR) ・ Attn				

COMPRESSOR				
RATED PRESSURE	Mpa Kgf/cm2	Unload Condition	FAIR ・ Attn	
RATED AIR FLOW	m3/min	Receiver Tank Condition	FAIR ・ Attn	
Compressor Oil Leak	FAIR ・ Attn	Safety Valve Condition	FAIR ・ Attn	

CONDITION	(FAIR) ・ Attn	
E/G周りクーラント漏れあり AROUND ENGINE: COOLANT LEAKING		
電圧調整ダイアル回しても反応なし VOLTAGE ADJUSTMENT KNOB: NOT WORKING		

RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR ・WORN・ UNEVEN WEAR

COMMENTS

*1 ブロック周り油漏れあり AROUND ENGINE BLOCK: OIL LEAKING

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。