INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/10/19	MAKE	KUBOTA	MODEL	U-008-5
SERIAL	KBCAZ05AAN3G11875			STAMP	KBCAZ05AAN3G11875
HR METER	256 HR			YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / (NONE)			SHOE	180R

ENGINE : MODEL	D722	S/N	4NP0823
Oil leakage	(FAIR) · Attn		
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	(FAIR) · Attn		
Oil	(FAIR) · Attn		
Exhaust Color	(FAIR) · Attn		
US EPA	YES · (NO)		
MAIN PUMP			
Sound	(FAIR) · Attn		
Oil leakage	(FAIR) · Attn		
Power	(FAIR) · Attn		
COOLING SYSTEM			
Radiator	(FAIR) · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	(FAIR) · Attn		
Travel	(FAIR) · Attn		
INTERIOR	See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY		
Operator's Seat	(FAIR) · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · (None)		
BOOM / ARM / BKT			
Boom	(FAIR) · Attn		
Boom Cylinder	(FAIR) · Attn		
Arm	(FAIR) · Attn		
Arm Cylinder	(FAIR) · Attn		
ATTACHMENT	(FAIR) · Attn		
BKT Cylinder	(FAIR) · Attn		

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
COMMENT		
可変脚仕様 VARIABLE WIDTH UNDERCARRIAGE		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG · (WRIST)	
Multi	MULTI (· 2 ·) NO	
ARM-CRANE	YES · (NO)	
BLADE	(YES) · NO	
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	(YES) · NO	Breaker only (· Multi)
COMMENT		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。