INSPECTION SHEET 検品書

CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/10/27	MAKE	MOROOKA	MODEL	MST-800VDL
SERIAL	024068			STAMP	024068
HR METER	2569 HR	Odometer	– km	YEAR	YR
CAB/CNP	ROPS CAB (/ CAB /) ROPS CNP / CNP / NONE			SHOE	600R
TIRE					

ENGINE : MODEL	S/N	
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	

OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	

COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	

TRANSMISSION & TRAVEL				
T/M TYPE	(PS) · DD		No. OF GEARS	2 GEARS
Transmission	(FAIR) · Attn			
Travel	(FAIR) · Attn			
Swing	FAIR · Attn			
Articulate	FAIR · Attn			
FOOT BRAKE	FAIR · Attn			
PARKING BRAKE	(FAIR) · Attn			

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · (DIRTY)	
Operator's Seat	(FAIR) · Attn	
Glasses	FAIR · (Attn)	ドア下側欠 LOWER DOOR GLASS: MISSING
AirCon	(A/C) · H/C · H only · C only · None	

MAIN FRAME		
MAIN FLAME	(FAIR) · Attn	

VESSEL		
VESSEL	FAIR · (Attn)	*1
REAR GATE TYPE	NORMAL · L-GATE (FLAT)	
REAR GATE	FAIR · Attn	

UNDERCARRIAGE: See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR

COMMENT

*1 左右リフトシリンダー油漏れあり LIFT CYLINDERS: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。