INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/10/29	MAKE	KOMATSU	MODEL	PC40MR-3
SERIAL	UNKNOWN (PLATE: PAINTED)			STAMP	KMTPC203CFE023285
HR METER	3651 HR			YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / (CNP) / NONE			SHOE	350R

ENGINE : MODEL 4D88E S/N 36362		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
MAIN PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	FAIR · (Attn)	補修あり REPAIRED WITH SOME ADHESIVE TAPE
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
BOOM / ARM / BKT		
Boom	(FAIR) · Attn	
Boom Cylinder	(FAIR) · Attn	
Arm	FAIR · (Attn)	*1
Arm Cylinder	(FAIR) · Attn	
ATTACHMENT	FAIR · (Attn)	ガタあり LOOSE
BKT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	
COMMENT		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG · (WRIST)	
Multi	(MULTI) · 2 · NO	
ARM-CRANE	YES · (NO)	
BLADE	(YES) · NO	
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	(YES) · NO	Breaker only · (Multi)
COMMENT		
リペイントあり REPAINTED		
スイングブラケット亀裂あり SWING BRACKET: CRACKED		
*1 ガタ大、左右側面補修跡あり MUCH LOOSE, REPAIRED		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。