INSPECTION SHEET 検品書

TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2026/10/30	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE		
MAKE	HITACHI SUMITOMO		MODEL	UCX300	
SERIAL	UC030-6009		STAMP	UC030-6009	
HR METER	4918 HR	Odometer	UNKNOWN km	YEAR	2007 YR
CHASSIS	MODEL -	No. -		TIRE	11.00R20

ENGINE(CRANE) : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	

ENGINE(CHASSIS) : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	

OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	

COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	

OPERATING SYSTEM		
Computer	(OK) · NG	未確認 NOT CHECKED
Swing	FAIR · (Attn)	*1
Travel	(FAIR) · Attn	

TRANSMISSION & TRAVEL				
T/M TYPE	(AT) · MT		No. OF GEARS	2 GEARS
Transmission	(FAIR) · Attn			
No. of DRIVE WHEELS	4 WD			
Travel	(FAIR) · Attn			
FOOT BRAKE	(FAIR) · Attn			
PARKING BRAKE	(FAIR) · Attn			

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	破れあり TORN
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · NONE	

CRANE	
WEIGHT	1
HOOK	30t

BOOM		
MAIN BOOM	TOP, BOTTOM, 3m	
BOOM TOTAL	12m	
No. of Section	- SECTIONS	
TOP SHEAVE	YES · (NO)	
JIB	STD · PWR	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR (FAIR) · WORN · UNEVEN WEAR	

COMMENT

OUTRIGGERS		
OUTRIGGERS	FAIR · (Attn)	H-TYPE *2
FRONT JACK	YES · (NO)	

COMMENT

ホイールクレーン WHEELED CRANE
主巻ドラムのみ ONLY MAIN DRUM
汚れ大 MUCH DIRTY
付属品:手すり HANDRAILS AS SPARE
*1 旋回付近油漏れあり、旋回ロック不良
*1 AROUND SWING PART: OIL LEAKING, SWING LOCK: MALFUNCTION
*2 左縦シリンダー、アウトリガーラインF側油漏れあり
(左R縦シリンダー配管、配管ライン:メクラ処理あり)
*2 LEFT JACK CYLINDERS & FRONT OUTRIGGER LINE: OIL LEAKING
(REAR LEFT JACK CYLINDER PIPING
& FRONT OUTRIGGER PIPING LINE: CAPPED)

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。