INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/10/28	MAKE	HITACHI	MODEL	ZX75US-5B
SERIAL	HCMDEPA0T00075843		STAMP	HCMDEPA0T00075843	
HR METER	230 HR		YEAR	YR	
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL	S/N	
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	(YES) · NO	
MAIN PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
INTERIOR	See Photos. 写真参照	
INTERIOR COND.	(CLEAN) · FAIR · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	(FAIR) · Attn	
Boom Cylinder	(FAIR) · Attn	
Arm	(FAIR) · Attn	
Arm Cylinder	(FAIR) · Attn	
ATTACHMENT	(FAIR) · Attn	
BKT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5		
COMMENT			
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )		
Lever	LONG · (WRIST)		
Multi	(MULTI) · 2 · NO		
ARM-CRANE	YES · (NO)		
BLADE	(YES) · NO		
OFFSET	YES · (NO)		
OFFSET Cylinder	FAIR · Attn		
Piping	YES · (NO)	Breaker only · Multi	
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。