INSPECTION SHEET 検品書

ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/10/27	MAKE	KATO	MODEL	KR-25H-F
SERIAL No.	PLATE : 02A0549		STAMP : KRC017-0549		
HR METER	9016 HR		Odometer	34080 km	
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR・(Attn)	*1
Blow-By	(FAIR)・Attn	A LITTLE・MIDDLE・SEVERE
Sound	(FAIR)・Attn	
Oil	(FAIR)・Attn	
Exhaust Color	(FAIR)・Attn	
OPERATION PUMP		
Sound	(FAIR)・Attn	
Oil leakage	(FAIR)・Attn	
Power	(FAIR)・Attn	
COOLING SYSTEM		
Radiator	(FAIR)・Attn	
Oil Cooler	(FAIR)・Attn	
OPERATING SYSTEM		
Computer	(OK)・NG	
Swing	(FAIR)・Attn	
Travel	(FAIR)・Attn	
TRANSMISSION		
Transmission	(FAIR)・Attn	
No. OF GEARS	4 GEARS	
4WD	(4WD)・6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・(FAIR)・DIRTY	
Operator's Seat	(FAIR)・Attn	
Glasses	(FAIR)・Attn	
AirCon	(A/C)・H/C・H only・C only・None	
COMMENT		

BOOM		
No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	(FAIR)・Attn	
DERRICKING CYL.	(FAIR)・Attn	
EXTENSION CYL.	(FAIR)・Attn	
JIB	(YES)・NO	
JIB TYPE	STD・(PWR)	
MAIN & SUB WIRE	(YES)・NO	
FREE FALL	YES・(NO)	
HOOK	25t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
TIRE WEAR	FAIR・(WORN)・UNEVEN WEAR	
COMMENT		
左Fタイヤ側面傷あり FRONT LEFT TIRE SIDEWALL: SCRATCHED		
OUTRIGGERS		
OUTRIGGERS	X・(H)	
OUTRIGGERS COND.	(FAIR)・Attn	
Oil leakage (JACK CYL.)	FRONT L・R	REAR L・R
Oil leakage (SLIDE CYL.)	FRONT L・R	REAR L・R
COMMENT		
F89エラー表示あり(旋回ポテンショ不良)		
"F89" ERROR DISPLAY FOR SLEWING POTENTIOMETER		
*1 E/G上部油漏れあり UPPER PART OF ENGINE: OIL LEAKING		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。