INSPECTION SHEET 検品書

ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/10/29	MAKE	TADANO	MODEL	GR-250N-3
SERIAL No.	PLATE : FB6984		STAMP : T007-0239		
HR METER	26804 HR		Odometer	110771 km	
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR (Attn)	*1
Blow-By	FAIR (Attn)	A LITTLE (MIDDLE) SEVERE
Sound	FAIR (Attn)	異音あり NOISES
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	FAIR (Attn)	ラジエータ内オイル混入あり OIL: MIXED
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Computer	(OK) · NG	
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
TRANSMISSION		
Transmission	(FAIR) · Attn	
No. OF GEARS	3 GEARS	
4WD	(4WD) · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	破れあり CUT
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
COMMENT		

BOOM		
No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	(FAIR) · Attn	
DERRICKING CYL.	(FAIR) · Attn	
EXTENSION CYL.	(FAIR) · Attn	
JIB	(YES) · NO	
JIB TYPE	STD · (PWR)	
MAIN & SUB WIRE	(YES) · NO	
FREE FALL	YES · (NO)	
HOOK	25t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	(FAIR) · WORN · UNEVEN WEAR	
COMMENT		
OUTRIGGERS		
OUTRIGGERS	(X) · H	
OUTRIGGERS COND.	(FAIR) · Attn	
Oil leakage (JACK CYL.)	FRONT L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R	REAR L · R
COMMENT		
*1 E/Gブロックにじみあり ENGINE BLOCK: OIL OOZING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。