INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/11/4	MAKE	CAT	MODEL	950MZ
SERIAL	CAT0950MKHE820163		STAMP	CAT0950MKHE820163	
HR METER	12539 HR	Odometer	63825 km	YEAR	YR
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	23.5-25	

ENGINE : MODEL C7.1 S/N J7A01284		
Oil leakage	(FAIR) · Attn	
Blow-By	FAIR · (Attn)	A LITTLE · MIDDLE · (SEVERE)
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	(YES) · NO	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
FOOT BRAKE	(FAIR) · Attn	
PARKING BRAKE	FAIR · (Attn)	効かない MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	FAIR · (Attn)	*1
AirCon	(A/C) · H/C · H only · C only · None	
FRONT & CYLINDERS		
Arm	(FAIR) · Attn	
Bell crank	(FAIR) · Attn	
Bucket	(FAIR) · Attn	
Articulate	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		
TIRE WEAR	(FAIR) · WORN · UNEVEN WEAR		
COMMENT			
STEERING TYPE	(WHEEL STEERING) / COMMAND STEERING / LEVER STEERING		
RIDE CONTROL	(YES) · NO		
ATTACHMENTS			
STD BKT	(YES) · OTHER		
BLADE	YES · (NO)	Piping for Tilt	YES · (NO)
COMMENT			
オイルフィルター周り作動油漏れあり			
AROUND OIL FILTER: HYDRAULIC OIL LEAKING			
E/Gチェックランプ、DPFランプ、！マーク点灯あり			
CHECK ENGINE LAMP, DPF LAMP, & WARNING LAMP: ON			
データリンク障害、排ガス障害表示あり			
WARNINGS DISPLAY FOR DATA LINK & EXHAUST GAS			
*1 左ドアガラス欠、F正面、F左側割れあり			
*1 SOME LEFT UPPER DOOR GLASS: MISSING, WINDSHIELD: CRACKED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。