

INSPECTION SHEET 検品書
ASPHALT FINISHER アスファルトフィニッシャー

INSPECTION DATE	2026/10/22	MAKE	SUMITOMO	MODEL	HA60W-5
SERIAL	A60A5-0109			STAMP	A60A5-0109
HR METER	8505	HR	YEAR	YR	
SHOE		TIRE (REAR)	15.5R25	MAX PAVING WIDTH	6200 mm

ENGINE : MODEL S/N <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Oil leakage</td> <td style="width: 10%; text-align: center;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Blow-By</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td>A LITTLE ・ MIDDLE ・ SEVERE</td> </tr> <tr> <td>Sound</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Oil</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Exhaust Color</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>US EPA</td> <td>YES</td> <td style="text-align: center;">NO</td> <td></td> </tr> </table> OPERATION PUMP <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Sound</td> <td style="width: 10%; text-align: center;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Oil leakage</td> <td style="text-align: center;">FAIR</td> <td style="text-align: center;">Attn</td> <td>にじみあり OIL OOZING</td> </tr> <tr> <td>Power</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> </table> COOLING SYSTEM <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Radiator</td> <td style="width: 10%; text-align: center;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Oil Cooler</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> </table> OPERATING SYSTEM <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">TRAVEL</td> <td style="width: 10%; text-align: center;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>SCREED(R)</td> <td style="text-align: center;">FAIR</td> <td style="text-align: center;">Attn</td> <td>*1</td> </tr> <tr> <td>SCREED(L)</td> <td style="text-align: center;">FAIR</td> <td style="text-align: center;">Attn</td> <td>*1</td> </tr> <tr> <td>VIBRATION</td> <td style="text-align: center;">FAIR</td> <td style="text-align: center;">Attn</td> <td>動作しない NOT WORKING</td> </tr> <tr> <td>TAMPER</td> <td style="text-align: center;">FAIR</td> <td style="text-align: center;">Attn</td> <td>動作しない NOT WORKING</td> </tr> <tr> <td>SPREADER(R)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>SPREADER(L)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>HOPPER(R)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>HOPPER(L)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>FEEDER</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> </table>	Oil leakage	FAIR	Attn		Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE	Sound	FAIR	Attn		Oil	FAIR	Attn		Exhaust Color	FAIR	Attn		US EPA	YES	NO		Sound	FAIR	Attn		Oil leakage	FAIR	Attn	にじみあり OIL OOZING	Power	FAIR	Attn		Radiator	FAIR	Attn		Oil Cooler	FAIR	Attn		TRAVEL	FAIR	Attn		SCREED(R)	FAIR	Attn	*1	SCREED(L)	FAIR	Attn	*1	VIBRATION	FAIR	Attn	動作しない NOT WORKING	TAMPER	FAIR	Attn	動作しない NOT WORKING	SPREADER(R)	FAIR	Attn		SPREADER(L)	FAIR	Attn		HOPPER(R)	FAIR	Attn		HOPPER(L)	FAIR	Attn		FEEDER	FAIR	Attn		UNDERCARRIAGE : See Photos. 写真参照 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 85%;">RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="width: 15%; text-align: center;">3</td> </tr> <tr> <td>TIRE WEAR</td> <td>FAIR ・ WORN ・ UNEVEN WEAR</td> </tr> </table> COMMENT SCREED WIDTH <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">MAIN SCREED</td> <td style="width: 20%; text-align: center;">2.5</td> <td style="width: 40%; text-align: right;">m</td> </tr> <tr> <td>WITH AUTO-WIDENER</td> <td></td> <td style="text-align: right;">m</td> </tr> <tr> <td>WITH EXTENSION</td> <td style="text-align: center;">6.2</td> <td style="text-align: right;">m</td> </tr> <tr> <td>LEVEL SENSOR</td> <td>YES ・ NO</td> <td></td> </tr> </table> COMMENT コントロールバルブ油漏れあり CONTROL VALVE: OIL LEAKING オイルフィルターホース油漏れあり OIL FILTER HOSE: OIL LEAKING フットブレーキ踏み続けるとすぐに油圧が抜ける FOOT BRAKE: LOSS OF HYDRAULIC BRAKE PRESSURE WHEN KEEPING STEPPING ON THE PEDAL パーキング効かない PARKING BRAKE: MALFUNCTION *1 ガイドシリンダーメッキ剥がれあり GUIDE CYLINDER: COATING PEELED	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR	MAIN SCREED	2.5	m	WITH AUTO-WIDENER		m	WITH EXTENSION	6.2	m	LEVEL SENSOR	YES ・ NO	
Oil leakage	FAIR	Attn																																																																																																			
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE																																																																																																		
Sound	FAIR	Attn																																																																																																			
Oil	FAIR	Attn																																																																																																			
Exhaust Color	FAIR	Attn																																																																																																			
US EPA	YES	NO																																																																																																			
Sound	FAIR	Attn																																																																																																			
Oil leakage	FAIR	Attn	にじみあり OIL OOZING																																																																																																		
Power	FAIR	Attn																																																																																																			
Radiator	FAIR	Attn																																																																																																			
Oil Cooler	FAIR	Attn																																																																																																			
TRAVEL	FAIR	Attn																																																																																																			
SCREED(R)	FAIR	Attn	*1																																																																																																		
SCREED(L)	FAIR	Attn	*1																																																																																																		
VIBRATION	FAIR	Attn	動作しない NOT WORKING																																																																																																		
TAMPER	FAIR	Attn	動作しない NOT WORKING																																																																																																		
SPREADER(R)	FAIR	Attn																																																																																																			
SPREADER(L)	FAIR	Attn																																																																																																			
HOPPER(R)	FAIR	Attn																																																																																																			
HOPPER(L)	FAIR	Attn																																																																																																			
FEEDER	FAIR	Attn																																																																																																			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																				
TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR																																																																																																				
MAIN SCREED	2.5	m																																																																																																			
WITH AUTO-WIDENER		m																																																																																																			
WITH EXTENSION	6.2	m																																																																																																			
LEVEL SENSOR	YES ・ NO																																																																																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 85%;">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="width: 15%; text-align: center;">3</td> </tr> </table>				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。