INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/10/22	CATEGORY	セメントミルクプラント（電気式） CEMENT MILK MIXING PLANT (ELECTRIC TYPE)				
MAKE	AVOLON			MODEL	AM-750WF-65TV-180		
SERIAL	62315			STAMP	NOT FOUND		
HR METER	- HR	Odometer	km	YEAR	YR		
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / (NONE)	SHOE		TIRE			

ENGINE	MODEL		S/N		
Oil leakage	FAIR ・ Attn		Oil	FAIR ・ Attn	
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE	Exhaust Color	FAIR ・ Attn	
Sound	FAIR ・ Attn		EPA	YES ・ NO	

CONDITION	FAIR (・) Attn	

未確認 OPERATION: NOT CHECKED

UNDERCARRIAGE : See Photos. 写真参照			
RUST（5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED）	-	TIRE WEAR	FAIR ・WORN・ UNEVEN WEAR

COMMENT

コンクリート汚れあり CONCRETE STAINS

RUST of BODY（5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED）	3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。