

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/10/20	MAKE	HITACHI	MODEL	ZX200LC-3
SERIAL	HCM1U100A00224717			STAMP	HCM1U100A00224717
HR METER	3915	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600FLAT

ENGINE : MODEL		4HK1	S/N	808887
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn	オイル混入あり OIL: MIXED INTO THE COOLANT	
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	ガタあり SWING: LOOSE	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN		FAIR ・ DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C		H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	右側にじみあり RIGHT CYLINDER: OIL OOZING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	*1	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4
COMMENT					
BKT	STD / SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG	▪	(WRIST)		
Multi	MULTI	▪	2	▪	(NO)
ARM-CRANE	YES	▪	(NO)		
BLADE	YES	▪	(NO)		
OFFSET	YES	▪	(NO)		
OFFSET Cylinder	FAIR	▪	Attn		
Piping	YES	▪	(NO)	Breaker only ▪ Multi	
COMMENT					
アタッチメント: マグネット(フォーク付) ATTACHMENT: MAGNET-FORK					
エレベータCAB ELEVATOR CAB					
リペイントあり REPAINTED					
燃料ホース漏れ小 FUEL HOSE: FUEL LEAKING					
*1 発電機回転低下で吸着不可					
*1 MAGNET: UNABLE TO ATTRACT					
DUE TO LOW GENERATOR ENGINE SPEED					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。