INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/10/26	CATEGORY	自走式木材破砕機 MOBILE WOOD CRUSHER				
MAKE	HITACHI			MODEL	ZR130HC		
SERIAL	HCM8HY00A00008118			STAMP	NOT FOUND		
HR METER	9115 HR	Odometer	km	YEAR	2007 YR		
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / (NONE)	SHOE	500G	TIRE			

ENGINE	MODEL		S/N	
Oil leakage	(FAIR) · Attn		Oil	(FAIR) · Attn
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	(FAIR) · Attn
Sound	(FAIR) · Attn		EPA	YES · (NO)

CONDITION	(FAIR) · Attn	
スクリーン開閉シリンダー右側油漏れ、サビあり RIGHT SCREEN OPENING/CLOSING CYLINDER: OIL LEAKING, RUSTY		

UNDERCARRIAGE : See Photos. 写真参照			
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR · WORN · UNEVEN WEAR

COMMENT

ポンプ油漏れ小 PUMP: OIL LEAKING

HRメーター見えづらい HR METER: HARD TO READ

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。