INSPECTION SHEET 検品書
MOTOR GRADER グレーダー

INSPECTION DATE	2026/10/27	MAKE	MITSUBISHI	MODEL	MG500S
SERIAL	5G100107			STAMP	5G100107
HR METER	4143 HR	Odometer	47056 km	YEAR	YR
SCARIFIER	YES ・ (NO)			BLADE	4000 mm
CAB/CNP	(CAB) / CNP / NONE			TIRE SIZE	14.00-24

ENGINE : MODEL		S/N 147920
Oil leakage	(FAIR)・Attn	
Blow-By	(FAIR)・Attn	A LITTLE・MIDDLE・SEVERE
Sound	(FAIR)・Attn	
Oil	(FAIR)・Attn	
Exhaust Color	(FAIR)・Attn	
US EPA	YES・(NO)	
OPERATION PUMP		
Sound	(FAIR)・Attn	
Oil leakage	(FAIR)・Attn	
Power	(FAIR)・Attn	
COOLING SYSTEM		
Radiator	(FAIR)・Attn	
Oil Cooler	(FAIR)・Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS)・DD	
Transmission	(FAIR)・Attn	
Travel	(FAIR)・Attn	
FOOT BRAKE	(FAIR)・Attn	
PARKING BRAKE	(FAIR)・Attn	
INTERIOR	See Photos. 写真参照	
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・Attn	
Glasses	(FAIR)・Attn	
AirCon	A/C ・ H/C ・ (H only) ・ C only ・ None	
HYD. CYLINDER		
For Blade	FAIR・(Attn)	スライドシリンダーサビあり SLIDE CYLINDER: RUSTY
For Scarifier	FAIR ・ Attn	
Articulate	(FAIR)・Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR (FAIR)・WORN・UNEVEN WEAR	
COMMENT	
左右Fタイヤエアーが少ない	
AIR PRESSURE OF FRONT TIRES: NOT ENOUGH	
リペイントあり REPAINTED	
左側サークルリフトシリンダーにじみあり	
LEFT CIRCLE LIFT CYLINDER: OIL OOZING	
サークルスイングシリンダー油漏れあり	
CIRCLE SWING CYLINDER: OIL LEAKING	
ブレーキチェックランプ点灯あり WARNING LAMP FOR BRAKE: ON	
エアー溜まりにくい AIR: HARD TO STORE	
ゲージ溜まってなくてもパーキング解除できる(メーター不良?)	
ABLE TO RELEASE THE PARKING BRAKE	
EVEN PRESSURE GAUGE ON MONITOR IS NOT ENOUGH	
(PRESSURE GAUGE: MALFUNCTION?)	
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。