# INSPECTION SHEET 検品書

## GENERATOR / COMPRESSOR / WELDER 発電機･コンプレッサー･ウェルダー

| INSPECTION DATE | 2026/10/28 | CATEGORY | GENERATOR / (COMPRESSOR) / WELDER |
|---|---|---|---|
| MAKE | DENYO | MODEL | DIS-550HB |
| SERIAL | 3689734 | STAMP | NOT FOUND |
| HR METER | 856 HR | TIRE SIZE | YEAR YR |

| ENGINE : MODEL | HINO H07C | S/N | |
|---|---|---|---|
| Oil leakage | FAIR ･(Attn) *1 | Oil | (FAIR) ･ Attn |
| Blow-By | (FAIR) ･ Attn A LITTLE ･ MIDDLE ･ SEVERE | Exhaust Color | (FAIR) ･ Attn |
| Sound | (FAIR) ･ Attn | Radiator | (FAIR) ･ Attn |

| GENERATOR | | | | | |
|---|---|---|---|---|---|
| RATED POWER | KVA | Leaking Breaker Condition | FAIR ･ Attn | | |
| RATED AMPERE | A | Insulation Condition | FAIR ･ Attn | | |
| Output Terminal | FAIR ･ Attn | | | | |

| COMPRESSOR | | | | | |
|---|---|---|---|---|---|
| RATED PRESSURE | 1.03 (Mpa) Kgf/cm2 | Unload Condition | (FAIR) ･ Attn | | |
| RATED AIR FLOW | 15.6 m3/min | Receiver Tank Condition | (FAIR) ･ Attn | | |
| Compressor Oil Leak | (FAIR) ･ Attn | Safety Valve Condition | (FAIR) ･ Attn | | |

| CONDITION | (FAIR) ･ Attn |
|---|---|
| | |
| | |

| RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | TIRE WEAR | FAIR ･ WORN ･ UNEVEN WEAR |
|---|---|---|---|

**COMMENTS**

*1 ヘッド周りにじみあり AROUND CYLINDER HEAD: OIL OOZING

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。