INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/10/28	MAKE	ジャパニック JAPANIC	MODEL	8MEX-Ⅱ
SERIAL No.	PLATE : 22926		STAMP : NOT FOUND		
HR METER	902 HR	Odometer	– km	YEAR	YR
CHASSIS	MODEL –		No. –		
SHOE			TIRE SIZE	6.50-16	
MAX HIGHT	UNKNOWN m		MAX WEIGHT	UNKNOWN kg	

ENGINE : MODEL S/N		
Oil leakage	FAIR ・ Attn	
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR ・ Attn	
Oil	FAIR ・ Attn	
Exhaust Color	FAIR ・ Attn	
US EPA	YES ・ NO	
OPERATION PUMP		
Sound	(FAIR) ・ Attn	
Oil leakage	(FAIR) ・ Attn	
Power	(FAIR) ・ Attn	
COOLING SYSTEM		
Radiator	FAIR ・ Attn	
Oil Cooler	FAIR ・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(AT) ・ MT	No. OF GEARS 2 GEARS
Transmission	(FAIR) ・ Attn	
4WD	4WD ・ 2WD	
Travel	(FAIR) ・ Attn	
Swing	FAIR ・ Attn	
FOOT BRAKE	FAIR ・ Attn	
PARKING BRAKE	FAIR ・ Attn	
BOOM		
No. of Section	– SECTIONS	
DERRICKING CYL.	(FAIR) ・ Attn	
EXTENSION CYL.	FAIR ・ Attn	

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	FAIR ・ Attn	
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・ (None)	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	(FAIR) ・ WORN ・ UNEVEN WEAR	
COMMENT		
OUTRIGGERS	X ・ H	
OUTRIGGERS COND.	FAIR ・ Attn	
COMMENT		
電動式 ELECTRIC TYPE		
リペイントあり REPAINTED		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。