INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2026/10/28	MAKE	TOYOTA	MODEL	6FD20
SERIAL	6FD25-39696			STAMP	6FD25-39696
HR METER	18301 HR	Odometer	- km	YEAR	YR
CAB/CNP	CAB / (CNP) / NONE			TIRE SIZE	F: 5.50-15 (DOUBLE) R: 6.00-9
MAX LIFTING HEIGHT	3.0 m	(VIEW) / MONO		FORK LENGTH	910 mm
FORK SPEC					

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · (DD)	
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
FOOT BRAKE	(FAIR) · Attn	
PARKING BRAKE	(FAIR) · Attn	
INTERIOR	See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · (DIRTY)	
Operator's Seat	(FAIR) · Attn	破れあり CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
HYDRAULICS		
MAST Cylinder	(FAIR) · Attn	
TILT Cylinder	FAIR · (Attn)	*1

UNDERCARRIAGE : See Photos. 写真参照	
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR (FAIR) · WORN · UNEVEN WEAR	

COMMENT

ステアリングシリンダーにじみあり STEERING CYLINDER: OIL OOZING

*1 右シリンダーにじみあり RIGHT CYLINDER: OIL OOZING

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。