INSPECTION SHEET 検品書
MOTOR GRADER グレーダー

INSPECTION DATE	2026/10/23	MAKE	KOMATSU	MODEL	GD505A-3
SERIAL	1623			STAMP	G50A3-1623
HR METER	9951 HR	Odometer	16432 km	YEAR	YR
SCARIFIER	(YES) ・ NO	5		BLADE	3700 mm
CAB/CNP	(CAB) / CNP / NONE			TIRE SIZE	14.00-24

ENGINE : MODEL	S/N	
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS)・ DD	
Transmission	FAIR ・(Attn)	油漏れあり OIL LEAKING
Travel	(FAIR)・ Attn	
FOOT BRAKE	(FAIR)・ Attn	
PARKING BRAKE	(FAIR)・ Attn	
INTERIOR	**See Photos. 写真参照**	
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	破れあり CUTS
Glasses	(FAIR)・ Attn	
AirCon	A/C ・ H/C ・ (H only) ・ C only ・ None	
HYD. CYLINDER		
For Blade	(FAIR)・ Attn	
For Scarifier	(FAIR)・ Attn	
Articulate	FAIR ・(Attn)	*2

UNDERCARRIAGE : See Photos. 写真参照	
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR (FAIR) ・ WORN ・ UNEVEN WEAR	

COMMENT

左右サークルリフトシリンダーにじみあり

CIRCLE LIFT CYLINDERS: OIL OOZING

CAB下バルブにじみあり VALVE UNDER CAB: OIL OOZING

CAB下辺りからエアー漏れあり AROUND BOTTOM OF CAB: AIR LEAKING

*1 オイルパン、ヘッドにじみあり OIL PAN & CYLINDER HEAD: OIL OOZING

*2 左側油漏れ、サビあり LEFT CYLINDER: OIL LEAKING, RUSTY

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。