INSPECTION SHEET 検品書

ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/10/29	MAKE	TADANO	MODEL	GR-250N-1
SERIAL No.	PLATE : FB5180		STAMP : TR256-1889		
HR METER	19796 HR		Odometer	108717 km	
TIRE SIZE	385-95R25		YEAR	YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR ・ Attn	
Blow-By	FAIR (Attn)	A LITTLE (・ MIDDLE ・) SEVERE
Sound	FAIR ・ Attn	
Oil	FAIR ・ Attn	
Exhaust Color	FAIR ・ Attn	
OPERATION PUMP		
Sound	FAIR ・ Attn	
Oil leakage	FAIR ・ Attn	
Power	FAIR ・ Attn	
COOLING SYSTEM		
Radiator	FAIR ・ Attn	
Oil Cooler	FAIR ・ Attn	
OPERATING SYSTEM		
Computer	OK ・ NG	
Swing	FAIR ・ Attn	
Travel	FAIR ・ Attn	
TRANSMISSION		
Transmission	FAIR ・ Attn	
No. OF GEARS	4 GEARS	
4WD	4WD ・ 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	FAIR ・ Attn	破れあり HUGE CUTS
Glasses	FAIR ・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	
COMMENT		

BOOM		
No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	FAIR ・ Attn	
DERRICKING CYL.	FAIR ・ Attn	
EXTENSION CYL.	FAIR ・ Attn	
JIB	YES ・ NO	
JIB TYPE	STD ・ PWR	
MAIN & SUB WIRE	YES ・ NO	
FREE FALL	YES ・ NO	
HOOK	25t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)		3
TIRE WEAR	FAIR (・ WORN ・) UNEVEN WEAR	
COMMENT		

OUTRIGGERS					
OUTRIGGERS	X ・ H				
OUTRIGGERS COND.	FAIR ・ Attn				
Oil leakage (JACK CYL.)	FRONT	L ・ R	REAR	L ・ R	
Oil leakage (SLIDE CYL.)	FRONT	L ・ R	REAR	L ・ R	
COMMENT					
バッテリー上カバー欠品 TOP COVER OF BATTERY BOX: MISSING					
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。