INSPECTION SHEET 検品書

TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2026/10/29	CATEGORY	(TRUCK CRANE) / ALL TERRAIN CRANE				
MAKE	TADANO			MODEL	TS-75M-1		
SERIAL	366347			STAMP	FK415E-550008		
HR METER	UNKNOWN HR	Odometer	46224 km	YEAR	YR		
CHASSIS	MODEL U-FK415ED改	No.	550008	TIRE	7.50-16		

ENGINE(CRANE) : MODEL		S/N
Oil leakage	FAIR ・ Attn	
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR ・ Attn	
Oil	FAIR ・ Attn	
Exhaust Color	FAIR ・ Attn	

ENGINE(CHASSIS) : MODEL 6D14		S/N
Oil leakage	FAIR ・ (Attn)	E/Gヘッドにじみあり CYLINDER HEAD: OIL OOZING
Blow-By	(FAIR) ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR) ・ Attn	
Oil	(FAIR) ・ Attn	
Exhaust Color	FAIR ・ (Attn)	白煙大 MUCH WHITE FUMES

OPERATION PUMP		
Sound	(FAIR) ・ Attn	
Oil leakage	(FAIR) ・ Attn	
Power	(FAIR) ・ Attn	

COOLING SYSTEM		
Radiator	FAIR ・ (Attn)	ラジエータ内サビあり INSIDE: RUSTY
Oil Cooler	(FAIR) ・ Attn	

OPERATING SYSTEM		
Computer	(OK) ・ NG	
Swing	(FAIR) ・ Attn	
Travel	(FAIR) ・ Attn	

TRANSMISSION & TRAVEL				
T/M TYPE	AT ・ (MT)		No. OF GEARS	5 GEARS
Transmission	(FAIR) ・ Attn			
No. of DRIVE WHEELS	2 WD			
Travel	(FAIR) ・ Attn			
FOOT BRAKE	(FAIR) ・ Attn			
PARKING BRAKE	(FAIR) ・ Attn			

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR) ・ Attn	破れあり A LITTLE DAMAGED
Glasses	(FAIR) ・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ NONE	

CRANE	
WEIGHT	-
HOOK	4.9t, BALL

BOOM		
MAIN BOOM		
BOOM TOTAL		
No. of Section	4 SECTIONS	
TOP SHEAVE	(YES) ・ NO	
JIB	STD ・ PWR	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	(FAIR) ・ WORN ・ UNEVEN WEAR

COMMENT

OUTRIGGERS

OUTRIGGERS	(FAIR) ・ Attn	F: H-TYPE, R: X-TYPE
FRONT JACK	(YES) ・ NO	

COMMENT

CAB内張り剥がれあり INSIDE COVER OF CEILING OF CAB: PEELED OFF

穴あり HOLES

フリーフォール付 FREE FALL: YES

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。