INSPECTION SHEET 検品書

ASPHALT FINISHER　アスファルトフィニッシャー

INSPECTION DATE	2026/10/29	MAKE	CAT	MODEL	MF31WD
SERIAL	A8H07153	STAMP	A8H07153		
HR METER	E7600 HR	YEAR	YR		
SHOE		TIRE (REAR)	13.5-20	MAX PAVING WIDTH	3200 mm

ENGINE : MODEL	S/N	
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR) ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR) ・ Attn	
Oil	(FAIR) ・ Attn	
Exhaust Color	(FAIR) ・ Attn	
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR) ・ Attn	
Oil leakage	(FAIR) ・ Attn	
Power	(FAIR) ・ Attn	
COOLING SYSTEM		
Radiator	(FAIR) ・ Attn	
Oil Cooler	(FAIR) ・ Attn	
OPERATING SYSTEM		
TRAVEL	(FAIR) ・ Attn	
SCREED(R)	(FAIR) ・ Attn	
SCREED(L)	(FAIR) ・ Attn	
VIBRATION	(FAIR) ・ Attn	
TAMPER	FAIR ・ Attn	
SPREADER(R)	(FAIR) ・ Attn	
SPREADER(L)	(FAIR) ・ Attn	
HOPPER(R)	FAIR ・(Attn)	シリンダー油漏れあり　CYLINDER: OIL LEAKING
HOPPER(L)	(FAIR) ・ Attn	
FEEDER	(FAIR) ・ Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	(FAIR) ・ WORN ・ UNEVEN WEAR	
COMMENT		
SCREED WIDTH		
MAIN SCREED	1.8	m
WITH AUTO-WIDENER	–	m
WITH EXTENSION	3.2	m
LEVEL SENSOR	YES ・(NO)	
COMMENT		
E/G ヘッドカバー開閉跡あり		
E/G HEAD COVER: OPENED TRACES		
ステアリングインジケーター不良		
STEERING INDICATOR: MALFUNCTION		
HRメーターストップ　HR METER: STOPPED		
*1 ヘッド周り、インジェクター周り、アクセル周りにじみあり		
*1 AROUND CYLINDER HEAD & INJECTOR, ACCELERATOR: OIL OOZING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。