# INSPECTION SHEET 検品書

## ROUGH TERRAIN CRANE ラフタークレーン

| | | | | | |
|---|---|---|---|---|---|
| INSPECTION DATE | 2026/10/28 | MAKE | KATO | MODEL | KRM-13H-II |
| SERIAL No. | PLATE : 5810803 | | STAMP : KRC008-0803 | | |
| HR METER | 23076 HR | | Odometer | 128167 km | |
| TIRE SIZE | 275/80R22.5 | | YEAR | YR | |

| ENGINE : MODEL S/N | | |
|---|---|---|
| Oil leakage | FAIR・(Attn) | *1 |
| Blow-By | (FAIR)・Attn | A LITTLE・MIDDLE・SEVERE |
| Sound | (FAIR)・Attn | |
| Oil | (FAIR)・Attn | |
| Exhaust Color | (FAIR)・Attn | |
| **OPERATION PUMP** | | |
| Sound | (FAIR)・Attn | |
| Oil leakage | (FAIR)・Attn | |
| Power | (FAIR)・Attn | |
| **COOLING SYSTEM** | | |
| Radiator | (FAIR)・Attn | |
| Oil Cooler | (FAIR)・Attn | |
| **OPERATING SYSTEM** | | |
| Computer | (OK)・NG | |
| Swing | (FAIR)・Attn | |
| Travel | (FAIR)・Attn | |
| **TRANSMISSION** | | |
| Transmission | (FAIR)・Attn | |
| No. OF GEARS | 4 GEARS | |
| 4WD | (4WD)・6WD | |
| **INTERIOR See Photos. 写真参照** | | |
| INTERIOR COND. | CLEAN・(FAIR)・DIRTY | |
| Operator's Seat | (FAIR)・Attn | |
| Glasses | (FAIR)・Attn | |
| AirCon | (A/C)・H/C・H only・C only・None | |
| **COMMENT** | | |

| BOOM | | |
|---|---|---|
| No. of Section | 6 SECTIONS | |
| CRACK/ENFORCEMENT | (FAIR)・Attn | |
| DERRICKING CYL. | (FAIR)・Attn | |
| EXTENSION CYL. | (FAIR)・Attn | |
| JIB | (YES)・NO | |
| JIB TYPE | STD・(PWR) | |
| MAIN & SUB WIRE | (YES)・NO | |
| FREE FALL | YES・(NO) | |
| HOOK | 13t, BALL | |
| **UNDERCARRIAGE : See Photos. 写真参照** | | |
| **RUST**(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED) | | 4 |
| TIRE WEAR | (FAIR)・WORN・UNEVEN WEAR | |
| **COMMENT** | | |
| **OUTRIGGERS** | | |
| OUTRIGGERS | X・(H) | |
| OUTRIGGERS COND. | (FAIR)・Attn | |
| Oil leakage (JACK CYL.) | FRONT L・R | REAR L・R |
| Oil leakage (SLIDE CYL.) | FRONT L・R | REAR L・R |
| **COMMENT** | | |
| *1 E/G下部にじみあり BOTTOM OF ENGINE: OIL OOZING | | |
| **RUST of BODY**(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | 4 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。