

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/3/27	MAKE	CAT	MODEL	315GC-07A
SERIAL	CAT00315HLYW00348		STAMP	CAT00315HLYW00348	
HR METER	1215	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

<b>ENGINE : MODEL</b> C3.6 <b>S/N</b>	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	<input checked="" type="radio"/> YES · NO
<b>MAIN PUMP</b>	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
<b>COOLING SYSTEM</b>	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
<b>OPERATING SYSTEM</b>	
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
<b>INTERIOR See Photos. 写真参照</b>	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
<b>BOOM / ARM / BKT</b>	
Boom	<input checked="" type="radio"/> FAIR · Attn
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn
Arm	<input checked="" type="radio"/> FAIR · Attn
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn
BKT	<input checked="" type="radio"/> FAIR · Attn
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;">           BKT <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER (    )         </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;">           Lever LONG · <input checked="" type="radio"/> WRIST         </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;">           Multi <input checked="" type="radio"/> MULTI · 2 · NO         </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;">           ARM-CRANE <input checked="" type="radio"/> YES · NO プレート欠 NO PLATE         </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;">           BLADE YES · <input checked="" type="radio"/> NO         </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;">           OFFSET YES · <input checked="" type="radio"/> NO         </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;">           OFFSET Cylinder FAIR · Attn         </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;">           Piping YES · <input checked="" type="radio"/> NO Breaker only · Multi         </div>	
<b>COMMENT</b>	
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;">           RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         </div>	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。