

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/3/27	MAKE	CAT	MODEL	320D
SERIAL	CAT0320DVKAF00170		STAMP	CAT0320DVKAF00170	
HR METER	8848	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	黒煙あり BLACK FUMES
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	*1
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · Attn	
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	フひび割れあり UPPER WINDSHIELD: CRACKED
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	ガタあり LOOSE
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	ピンガタあり PIN: LOOSE
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	STD (SLOPE) NARROW / SKELETON / OTHER ()
Lever	LONG · (WRIST)
Multi	MULTI · 2 · (NO)
ARM-CRANE	YES · (NO)
BLADE	YES · (NO)
OFFSET	YES · (NO)
OFFSET Cylinder	FAIR · Attn
Piping	(YES) · NO Breaker only · (Multi) *2
COMMENT	
E/G掛かり悪い HARD TO START THE ENGINE	
左サイドカバーノブ欠 LEFT SIDE COVER KNOB: MISSING	
A/Cエラー表示あり A/C ERROR DISPLAY	
*1 サブタンク外れ、水漏れあり SUB TANK: COME OFF, WATER LEAKING	
*2 油圧配管右側ブーム背中側欠	
*2 RIGHT HOSE AT BOOM: PARTLY MISSING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。