

INSPECTION SHEET 検品書
EXCAVATOR バックホー

| | | | | | |
|-----------------|--|------|---------|-------------------|------------|
| INSPECTION DATE | 2024/3/29 | MAKE | HITACHI | MODEL | ZX225USR-6 |
| SERIAL | HCMDFCA0E00506118 | | STAMP | HCMDFCA0E00506118 | |
| HR METER | 6577 | HR | YEAR | YR | |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / CNP / NONE | | SHOE | 600G | |

ENGINE : MODEL 4HK1 **S/N** 787747

| | | | |
|---------------|---------------------------------------|--------|----------------------------|
| Oil leakage | <input checked="" type="radio"/> FAIR | · Attn | |
| Blow-By | <input checked="" type="radio"/> FAIR | · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | <input checked="" type="radio"/> FAIR | · Attn | |
| Oil | <input checked="" type="radio"/> FAIR | · Attn | |
| Exhaust Color | <input checked="" type="radio"/> FAIR | · Attn | |
| US EPA | <input checked="" type="radio"/> YES | · NO | |

MAIN PUMP

| | | | |
|-------------|---------------------------------------|--------|--|
| Sound | <input checked="" type="radio"/> FAIR | · Attn | |
| Oil leakage | <input checked="" type="radio"/> FAIR | · Attn | |
| Power | <input checked="" type="radio"/> FAIR | · Attn | |

COOLING SYSTEM

| | | | |
|------------|---------------------------------------|--------|--|
| Radiator | <input checked="" type="radio"/> FAIR | · Attn | |
| Oil Cooler | <input checked="" type="radio"/> FAIR | · Attn | |

OPERATING SYSTEM

| | | | |
|--------|---------------------------------------|--------|--|
| Swing | <input checked="" type="radio"/> FAIR | · Attn | |
| Travel | <input checked="" type="radio"/> FAIR | · Attn | |

INTERIOR See Photos. 写真参照

| | | | |
|-----------------|---------------------------------------|--------------------------------|--|
| Operator's Seat | <input checked="" type="radio"/> FAIR | · Attn | |
| Inside Cover | <input checked="" type="radio"/> FAIR | · Attn | |
| Glasses | <input checked="" type="radio"/> FAIR | · Attn | |
| AirCon | <input checked="" type="radio"/> A/C | · H/C · H only · C only · None | |

BOOM / ARM / BKT

| | | | |
|---------------|---------------------------------------|--------|--|
| Boom | <input checked="" type="radio"/> FAIR | · Attn | |
| Boom Cylinder | <input checked="" type="radio"/> FAIR | · Attn | |
| Arm | <input checked="" type="radio"/> FAIR | · Attn | |
| Arm Cylinder | <input checked="" type="radio"/> FAIR | · Attn | |
| BKT | <input checked="" type="radio"/> FAIR | · Attn | |
| BKT Cylinder | <input checked="" type="radio"/> FAIR | · Attn | |

UNDERCARRIAGE : See Photos. 写真参照

| | |
|--|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4 |
| COMMENT | |
| | |
| BKT | <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER() |
| Lever | LONG · <input checked="" type="radio"/> WRIST |
| Multi | <input checked="" type="radio"/> MULTI · 2 · NO |
| ARM-CRANE | <input checked="" type="radio"/> YES · NO *1 |
| BLADE | YES · <input checked="" type="radio"/> NO |
| OFFSET | YES · <input checked="" type="radio"/> NO |
| OFFSET Cylinder | FAIR · Attn |
| Piping | YES · <input checked="" type="radio"/> NO Breaker only · Multi |

COMMENT

*1 荷重計: エラ一点減あり ※要写真参照 ERROR DISPLAY

| | |
|--|--|
| | |
|--|--|

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。