

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2024/4/1		MAKE	KOMATSU	MODEL	D155AX-7	
SERIAL	90279			STAMP	KMT0D118CFC090279		
HR METER	7895	HR	SHOE	560G	YEAR	YR	
BLADE	STRAIGHT / <input checked="checked" type="radio"/> ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	<input checked="checked" type="radio"/> ROPS CAB / CAB / ROPS CNP / CNP / NONE			

<b>ENGINE : MODEL</b> 6D140E-6		<b>S/N</b> 732274	
Oil leakage	<input checked="checked" type="radio"/> FAIR · Attn		
Blow-By	<input checked="checked" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="checked" type="radio"/> FAIR · Attn		
Oil	<input checked="checked" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="checked" type="radio"/> FAIR · Attn		
US EPA	YES · <input checked="checked" type="radio"/> NO		
<b>OPERATION PUMP</b>			
Sound	<input checked="checked" type="radio"/> FAIR · Attn		
Oil leakage	<input checked="checked" type="radio"/> FAIR · Attn		
Power	<input checked="checked" type="radio"/> FAIR · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<input checked="checked" type="radio"/> FAIR · Attn		
Oil Cooler	<input checked="checked" type="radio"/> FAIR · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	<input checked="checked" type="radio"/> PS · DD	DIFF. STEERING	<input checked="checked" type="radio"/> YES · NO
Transmission	<input checked="checked" type="radio"/> FAIR · Attn		
Travel	<input checked="checked" type="radio"/> FAIR · Attn		
<b>INTERIOR See Photos. 写真参照</b>			
Operator's Seat	<input checked="checked" type="radio"/> FAIR · Attn		
Inside Cover	<input checked="checked" type="radio"/> FAIR · Attn		
Glasses	<input checked="checked" type="radio"/> FAIR · Attn		
AirCon	<input checked="checked" type="radio"/> A/C · H/C · H only · C only · None		
<b>BLADE &amp; CYLINDERS</b>			
BLADE	<input checked="checked" type="radio"/> FAIR · Attn		
CYLD.(R)	<input checked="checked" type="radio"/> FAIR · Attn		
CYLD.(L)	<input checked="checked" type="radio"/> FAIR · Attn		
TILT CYLD	<input checked="checked" type="radio"/> FAIR · Attn		
ANGLE CYLD	<input type="radio"/> FAIR · Attn		

<b>UNDERCARRIAGE See Photos. 写真参照</b>			
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
<b>COMMENT</b>			
Ripper	<input checked="checked" type="radio"/> MULTI · S/S	Shanks	2 PCS
Ripper CYLD.	<input checked="checked" type="radio"/> FAIR · Attn		
EQUALIZER BAR	<input type="radio"/> FAIR · Attn		
<b>COMMENT</b>			
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。