

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2024/4/1	MAKE	HITACHI	MODEL	KH180-3ED
SERIAL No.	PLATE : 242-1810	STAMP		7EKK04	
HR METER	6807	HR	SHOE	760G FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn	サビ大 MUCH RUSTY
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	<input type="radio"/> OK · <input type="radio"/> NG	未確認 NOT CHECKED
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 6m × 1, 3m × 2	
BOOM TOTAL	25m	
TOP SHEAVE	<input checked="" type="radio"/> YES · <input type="radio"/> NO	
JIB		
TOWER		

INTERIOR See Photos. 写真参照	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn 破れ大 DAMAGED
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
左右キヤタ緩みあり TRACK LINKS: WORN	
WEIGHT	3
HOOK	50t, BALL
LIFTER	YES · <input checked="" type="radio"/> NO
COMMENT	
油圧取出しあり W/EXTRA HYDRAULIC HOSES	
ウインチモーターホースにじみあり WINCH MOTOR HOSE: OIL OOZING	
主巻、補巻ワイヤー径違う(主巻が太い)	
DIAMETERS OF MAIN & AUXILIARY HOISTING WIRES: DIFFERENT (MAIN WIRE: THICKER)	
基礎仕様 FOUNDATION WORK MACHINE	
@NARITA YARD	
BOOM: TOP, BOTTOM, 6m × 1	
@SAKURA No.2 YARD	
BOOM: 3m × 2, KELLY BAR, KELLY DRIVE, HYDRAULIC TOOL, EXTRA WEIGHT, BALL HOOK, φ2200 DRILLING BUCKET	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。