

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/1	MAKE	KATO	MODEL	KR-25H-V3
SERIAL No.	PLATE :	3410084		STAMP :	KR257-0084
HR METER	12737	HR	Odometer	14020	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL S/N

Oil leakage	FAIR	<input type="radio"/>	Attn	*1
Blow-By	FAIR	<input type="radio"/>	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	<input type="radio"/>	Attn	
Oil	FAIR	<input type="radio"/>	Attn	
Exhaust Color	FAIR	<input type="radio"/>	Attn	

OPERATION PUMP

Sound	FAIR	<input type="radio"/>	Attn	
Oil leakage	FAIR	<input type="radio"/>	Attn	
Power	FAIR	<input type="radio"/>	Attn	

COOLING SYSTEM

Radiator	FAIR	<input type="radio"/>	Attn	
Oil Cooler	FAIR	<input type="radio"/>	Attn	

OPERATING SYSTEM

Computer	OK	<input type="radio"/>	NG	
Swing	FAIR	<input type="radio"/>	Attn	*2
Travel	FAIR	<input type="radio"/>	Attn	

TRANSMISSION

Transmission	FAIR	<input type="radio"/>	Attn		
No. OF GEARS	4	GEARS			
No. of DRIVE WHEELS	4	WD			

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR	<input type="radio"/>	Attn	
Inside Cover	FAIR	<input type="radio"/>	Attn	
Glasses	FAIR	<input type="radio"/>	Attn	*3
AirCon	A/C	<input type="radio"/>	H/C · H only · C only · None	

COMMENT

BOOM

No. of Section	4	SECTIONS	
CRACK/ENFORCEMENT	FAIR	<input type="radio"/>	Attn
DERRICKING CYL.	FAIR	<input type="radio"/>	Attn
EXTENSION CYL.	FAIR	<input type="radio"/>	Attn
JIB	YES	<input type="radio"/>	NO
JIB TYPE	STD	<input type="radio"/>	PWR
MAIN & SUB WIRE	YES	<input type="radio"/>	NO
HOOK	25t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

左右フステアリングシリンダー油漏れあり
FRONT STEERING CYLINDERS: OIL LEAKING

OUTRIGGERS

OUTRIGGERS	X	<input type="radio"/>	H	
OUTRIGGERS COND.	FAIR	<input type="radio"/>	Attn	

COMMENT

主巻ウインチモーター油漏れあり WINCH MOTOR FOR MAIN WIRE: OIL LEAKING
カウンターウエイトカバー割れあり COUNTER WEIGHT COVER: CRACKED
*1 オイルパン下油漏れあり LOWER PART OF OIL PAN: OIL LEAKING
*2 スイベル下油漏れあり BOTTOM OF SWIVEL: OIL LEAKING
*3 運転席右ガラスなし
*3 SOME RIGHT SIDE GLASS & DOOR GLASS: MISSING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。