

INSPECTION SHEET 検品書  
ROLLER ローラー

INSPECTION DATE	2024/4/1	MAKE	KAWASAKI	MODEL	K20 II
SERIAL	NO PLATE		STAMP	KR20D-2303	
HR METER	2383	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <b>CNP</b> / NONE		TIRE SIZE	9.00-20	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
<b>OPERATION PUMP</b>		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
<b>TRANSMISSION &amp; TRAVEL</b>		
T/M TYPE	PS · <input checked="" type="radio"/> DD	
Transmission	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn	
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn	
<b>INTERIOR</b> See Photos. 写真参照		
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None	
<b>OTHERS</b>		
Vibratory	<input checked="" type="radio"/> FAIR · Attn	
Watering	<input checked="" type="radio"/> FAIR · Attn *1	
Articulate	<input checked="" type="radio"/> FAIR · Attn	

<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
CNP 亀裂あり CNP TOP: MUCH CRACKED	
E/Gフードヒンジ破損あり SOME ENGINE HOOD HINGE: BROKEN	
*1 呼び水キャップ固着のため未確認	
*1 NOT CHECKED (PRIMING CAP: STUCK)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。