

INSPECTION SHEET 検品書  
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2024/3/29	MAKE	KATO	MODEL	NK-160C
SERIAL No.	PLATE : 0160	STAMP		NOT FOUND	
HR METER	UNKNOWN HR	SHOE	600G FLAT	YEAR	YR

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	白煙あり WHITE FUMES
<b>OPERATION PUMP</b>		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Computer	<input checked="" type="radio"/> OK · NG	
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
<b>BOOM</b>		
MAIN BOOM		
BOOM TOTAL		
TOP SHEAVE		YES · <input checked="" type="radio"/> NO
JIB		
TOWER		

<b>INTERIOR</b>		<b>See Photos. 写真参照</b>
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり HUGE CUTS
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	天井ひび割れあり SKYLIGHT: CRACKED
AirCon	A/C · H/C · <input checked="" type="radio"/> H only · C only · None	
<b>UNDERCARRIAGE : See Photos. 写真参照</b>		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
<b>COMMENT</b>		
WEIGHT		
HOOK		16t × 1
LIFTER		YES · <input checked="" type="radio"/> NO
<b>COMMENT</b>		
3段ブーム 3-SECTION BOOM		
CAB		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。