

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/1	MAKE	KATO	MODEL	KR-25H-V5
SERIAL No.	PLATE :	5410066		STAMP :	KR258-0066
HR METER	19151	HR	Odometer	89075	km
TIRE SIZE	385/95R25		YEAR	YR	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	E/G下油漏れあり BOTTOM: OIL LEAKING
Blow-By	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
Oil	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
<b>OPERATION PUMP</b>		
Sound	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
Oil leakage	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	油圧ポンプ油漏れあり OIL LEAKING
Power	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
<b>OPERATING SYSTEM</b>		
Computer	<input checked="" type="radio"/> OK <input type="radio"/> NG	
Swing	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
Travel	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
<b>TRANSMISSION</b>		
Transmission	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
No. OF GEARS	4	GEARS
No. of DRIVE WHEELS	4	WD
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
Inside Cover	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
Glasses	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn	
AirCon	<input checked="" type="radio"/> A/C <input type="radio"/> H/C <input type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None	
<b>COMMENT</b>		
ヒーターポンプ油漏れあり HEATER PUMP: OIL LEAKING		

<b>BOOM</b>	
No. of Section	4 SECTIONS
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn
DERRICKING CYL.	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn にじみあり OIL OOZING
EXTENSION CYL.	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn
JIB	<input checked="" type="radio"/> YES <input type="radio"/> NO
JIB TYPE	STD <input type="radio"/> PWR <input checked="" type="radio"/>
MAIN & SUB WIRE	<input checked="" type="radio"/> YES <input type="radio"/> NO
HOOK	25t, BALL
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
<b>COMMENT</b>	
下周り左右サイドリペイントあり SIDE PANELS: REPAINTED	
<b>OUTRIGGERS</b>	
OUTRIGGERS	X <input checked="" type="radio"/> H
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR <input type="radio"/> Attn *1
<b>COMMENT</b>	
過巻装置不良 OVERWINDING PREVENTION: MALFUNCTION	
リターダ油漏れあり RETARDER: OIL LEAKING	
*1 縦シリンダー4本油漏れあり VERTICAL CYLINDERS: OIL LEAKING	
<b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b>	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。