

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

| | | | | | |
|-----------------|---|------|----------|-----------|-----------|
| INSPECTION DATE | 2024/4/2 | MAKE | HITACHI | MODEL | ZW250-6 |
| SERIAL | BANNEMA0P85C60117 | | | STAMP | 85C6-0117 |
| HR METER | 16753 | HR | Odometer | 49928 | km |
| CAB/CNP | <input checked="" type="radio"/> ROPS CAB / CAB / ROPS CNP / CNP / NONE | | | TIRE SIZE | 23.5R25 |

| ENGINE : MODEL | S/N |
|---------------------------|--|
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn |
| Blow-By | <input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE |
| Sound | <input checked="" type="radio"/> FAIR · Attn |
| Oil | <input checked="" type="radio"/> FAIR · Attn |
| Exhaust Color | <input checked="" type="radio"/> FAIR · Attn |
| US EPA | YES · <input checked="" type="radio"/> NO |
| OPERATION PUMP | |
| Sound | <input checked="" type="radio"/> FAIR · Attn |
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn |
| Power | <input checked="" type="radio"/> FAIR · Attn |
| COOLING SYSTEM | |
| Radiator | <input checked="" type="radio"/> FAIR · Attn |
| Oil Cooler | <input checked="" type="radio"/> FAIR · Attn |
| TRANSMISSION & TRAVEL | |
| T/M TYPE | <input checked="" type="radio"/> PS · DD |
| Transmission | <input checked="" type="radio"/> FAIR · Attn |
| Travel | <input checked="" type="radio"/> FAIR · Attn |
| FOOT BRAKE | <input checked="" type="radio"/> FAIR · Attn |
| PARKING BRAKE | <input checked="" type="radio"/> FAIR · Attn |
| INTERIOR See Photos. 写真参照 | |
| Operator's Seat | <input checked="" type="radio"/> FAIR · Attn |
| Inside Cover | <input checked="" type="radio"/> FAIR · Attn |
| Glasses | <input checked="" type="radio"/> FAIR · Attn |
| AirCon | <input checked="" type="radio"/> A/C · H/C · H only · C only · None |
| FRONT & CYLINDERS | |
| Arm | <input checked="" type="radio"/> FAIR · Attn |
| Bell crank | <input checked="" type="radio"/> FAIR · Attn |
| Bucket | <input checked="" type="radio"/> FAIR · Attn |
| Articulate | <input checked="" type="radio"/> FAIR · Attn |

| | |
|--|---|
| UNDERCARRIAGE : See Photos. 写真参照 | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4 |
| COMMENT | |
| | |
| | |
| | |
| STEERING TYPE | <input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING |
| RIDE CONTROL | <input checked="" type="radio"/> YES · NO |
| ATTACHMENTS | |
| STD BKT | <input checked="" type="radio"/> YES · OTHER |
| BLADE | YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO |
| COMMENT | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。