INSPECTION SHEET 検品書

ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/2	MAKE	TADANO	MODEL	GR-160N-2
SERIAL No.	PLATE : 526432		STAMP : T006-0318		
HR METER	20578 HR		Odometer	129300 km	
TIRE SIZE	325/95R24		YEAR	YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR (Attn)	上部油漏れあり UPPER PART: OIL LEAKING
Blow-By	FAIR (Attn)	A LITTLE・MIDDLE・(SEVERE)
Sound	(FAIR)・Attn	
Oil	(FAIR)・Attn	
Exhaust Color	FAIR (Attn)	白煙あり WHITE FUMES
OPERATION PUMP		
Sound	(FAIR)・Attn	
Oil leakage	(FAIR)・Attn	
Power	(FAIR)・Attn	
COOLING SYSTEM		
Radiator	(FAIR)・Attn	
Oil Cooler	(FAIR)・Attn	
OPERATING SYSTEM		
Computer	(OK)・NG	
Swing	(FAIR)・Attn	
Travel	(FAIR)・Attn	
TRANSMISSION		
Transmission	(FAIR)・Attn	
No. OF GEARS	4 GEARS	
No, of DRIVE WHEELS	4 WD	
INTERIOR See Photos. 写真参照		
Operator's Seat	(FAIR)・Attn	破れ小 TINY CUT
Inside Cover	(FAIR)・Attn	
Glasses	(FAIR)・Attn	
AirCon	(A/C)・H/C・H only・C only・None	
COMMENT		

BOOM		
No. of Section	6 SECTIONS	
CRACK/ENFORCEMENT	(FAIR)・Attn	
DERRICKING CYL.	(FAIR)・Attn	
EXTENSION CYL.	(FAIR)・Attn	
JIB	(YES)・NO	
JIB TYPE	(STD)・PWR	
MAIN & SUB WIRE	(YES)・NO	*1
HOOK	16t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
COMMENT		
右Rステアリングシリンダー油漏れあり		
REAR RIGHT STEERING CYLINDER: OIL LEAKING		
OUTRIGGERS		
OUTRIGGERS	X・(H)	
OUTRIGGERS COND.	FAIR・(Attn)	*2
COMMENT		
A/Cコンデンサー付近油漏れあり AROUND CONDENSOR OF A/C: OIL LEAKING		
エキゾーストパイプにじみあり EXHAUST PIPE: OIL OOZING		
*1 主巻ワイヤーキンク大 MAIN WIRE: MUCH KINKED		
*2 左右R縦シリンダー油漏れあり REAR VERTICAL CYLINDERS: OIL LEAKING		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。