

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/2	MAKE	KATO	MODEL	KR-10H
SERIAL No.	PLATE :	2511285		STAMP :	KR100-1285
HR METER	18000	HR	Odometer	99695	km
TIRE SIZE	11R22.5		YEAR	YR	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR <input checked="" type="radio"/> Attn *1	
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · <b>SEVERE</b>
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATION PUMP</b>		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATING SYSTEM</b>		
Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	
<b>TRANSMISSION</b>		
Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	4	GEARS
No. of DRIVE WHEELS	4	WD
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	破れあり CUT
Inside Cover	FAIR <input checked="" type="radio"/> Attn	
Glasses	FAIR <input checked="" type="radio"/> Attn	天井ガラス割れあり SKYLIGHT: CRACKED
AirCon	A/C	<b>H/C</b> · H only · C only · None
<b>COMMENT</b>		

<b>BOOM</b>	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn にじみあり OIL Oozing
JIB	YES <input type="radio"/> <b>NO</b> <input checked="" type="radio"/>
JIB TYPE	STD <input type="radio"/> PWR <input type="radio"/>
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO <input type="radio"/>
HOOK	4.9t, BALL
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
<b>OUTRIGGERS</b>	
OUTRIGGERS	X <input type="radio"/> <b>H</b> <input checked="" type="radio"/>
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn
<b>COMMENT</b>	
*1 オイルパン下周りにじみあり BOTTOM OF OIL PAN: OIL Oozing	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。