

INSPECTION SHEET 検品書

TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2024/4/2	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE			
MAKE	KATO		MODEL	NK-200H-V		
SERIAL	2710198		STAMP	KW45GMN-00219		
HR METER	3500 / ENGINE: 1173 HR	Odometer	5600 km	YEAR	YR	
CHASSIS	MODEL	KW450MN	No.	00219	TIRE	11.00R20 / 10.00R20

ENGINE(CRANE) : MODEL		S/N	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
ENGINE(CHASSIS) : MODEL		S/N	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Computer	OK · NG		
Swing	FAIR · Attn		
Travel	FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	AT · (MT)	No. OF GEARS	5 GEARS
Transmission	FAIR · Attn		
No. of DRIVE WHEELS	R4 WD		
Travel	FAIR · Attn		
FOOT BRAKE	FAIR · Attn		
PARKING BRAKE	FAIR · Attn		
INTERIOR See Photos. 写真参照			
Operator's Seat	FAIR · Attn	破れあり CUTS	
Inside Cover	FAIR · Attn	剥がれあり PEELED	
Glasses	FAIR · Attn		
AirCon	A/C (H/C) · H only · C only · NONE		

CRANE		
WEIGHT	-	
HOOK	20t, BALL	
BOOM		
MAIN BOOM		
BOOM TOTAL		
No. of Section	4 SECTIONS	
TOP SHEAVE	(YES) · NO	
JIB	(STD) · PWR	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5	
COMMENT		
Fバンパーヘコミあり FRONT BUMPER: DENT		
Rタイヤ側面傷あり REAR TIRE SIDEWALLS: CUTS		
OUTRIGGERS		
OUTRIGGERS	FAIR · (Attn) H-TYPE *1	
FRONT JACK	(YES) · NO	
COMMENT		
車幅灯破損あり SIDE LIGHTS: BROKEN		
E/Gストップ不良 ENGINE STOPPER: MALFUNCTION		
起伏シリンダー油漏れあり DERRICKING CYLINDER: OIL LEAKING		
*1 左F横シリンダー油漏れ、左右F縦シリンダーにじみあり		
*1 FRONT LEFT HORIZONTAL CYLINDER: OIL LEAKING,		
FRONT VERTICAL CYLINDERS: OIL Oozing		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。