

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

| | | | | | |
|-----------------|-----------------|---------|----------|------------|-------------|
| INSPECTION DATE | 2024/4/2 | MAKE | KATO | MODEL | KR-10H-L II |
| SERIAL No. | PLATE : 3910380 | STAMP : | | KR102-0380 | |
| HR METER | 11443 | HR | Odometer | 126153 | km |
| TIRE SIZE | 275/80R22.5 | YEAR | YR | | |

ENGINE : MODEL W04C S/N

| | |
|---------------|--|
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn |
| Blow-By | <input checked="" type="radio"/> FAIR · <input type="radio"/> Attn A LITTLE · MIDDLE · <input checked="" type="radio"/> SEVERE |
| Sound | <input checked="" type="radio"/> FAIR · Attn |
| Oil | <input checked="" type="radio"/> FAIR · Attn |
| Exhaust Color | <input checked="" type="radio"/> FAIR · Attn |

OPERATION PUMP

| | |
|-------------|--|
| Sound | <input checked="" type="radio"/> FAIR · Attn |
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn |
| Power | <input checked="" type="radio"/> FAIR · Attn |

COOLING SYSTEM

| | |
|------------|--|
| Radiator | <input checked="" type="radio"/> FAIR · Attn |
| Oil Cooler | <input checked="" type="radio"/> FAIR · Attn |

OPERATING SYSTEM

| | |
|----------|--|
| Computer | <input checked="" type="radio"/> OK · NG *1 |
| Swing | <input checked="" type="radio"/> FAIR · Attn |
| Travel | <input checked="" type="radio"/> FAIR · Attn |

TRANSMISSION

| | |
|---------------------|--|
| Transmission | <input checked="" type="radio"/> FAIR · Attn |
| No. OF GEARS | 4 GEARS |
| No. of DRIVE WHEELS | 4 WD |

INTERIOR See Photos. 写真参照

| | |
|-----------------|---|
| Operator's Seat | <input checked="" type="radio"/> FAIR · Attn |
| Inside Cover | <input checked="" type="radio"/> FAIR · Attn |
| Glasses | <input checked="" type="radio"/> FAIR · Attn |
| AirCon | <input checked="" type="radio"/> A/C · H/C · H only · C only · None |

COMMENT

| | |
|--|--|
| | |
| | |
| | |

BOOM

| | |
|-------------------|--|
| No. of Section | 6 SECTIONS |
| CRACK/ENFORCEMENT | <input checked="" type="radio"/> FAIR · Attn |
| DERRICKING CYL. | <input checked="" type="radio"/> FAIR · Attn |
| EXTENSION CYL. | <input checked="" type="radio"/> FAIR · Attn |
| JIB | <input checked="" type="radio"/> YES · NO |
| JIB TYPE | <input checked="" type="radio"/> STD · PWR |
| MAIN & SUB WIRE | <input checked="" type="radio"/> YES · NO |
| HOOK | 10t, BALL |

UNDERCARRIAGE : See Photos. 写真参照

| | |
|--|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4 |
|--|---|

COMMENT

| | |
|--|--|
| | |
| | |

OUTRIGGERS

| | |
|------------------|--|
| OUTRIGGERS | X · <input checked="" type="radio"/> H |
| OUTRIGGERS COND. | <input checked="" type="radio"/> FAIR · Attn |

COMMENT

| | |
|--|--|
| コントロールバルブ付近油漏れあり AROUND CONTROL VALVE: OIL LEAKING | |
| *1 モニター映らない、ACS非常にて作動確認済 | |
| *1 MONITOR: NOT DISPLAYING, | |
| NEED TO USE THE ACS EMERGENCY MODE TO OPERATE | |

| | |
|--|--|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| | |
|--|---|
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4 |
|--|---|

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。