

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/2	MAKE	TADANO	MODEL	GR-120N-2
SERIAL No.	PLATE : FD1845		STAMP : T005-0198		
HR METER	11761	HR	Odometer	81730	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL	S/N
Oil leakage <input type="radio"/> FAIR · Attn	
Blow-By <input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound <input type="radio"/> FAIR · Attn	
Oil <input type="radio"/> FAIR · Attn	
Exhaust Color <input type="radio"/> FAIR · Attn	
OPERATION PUMP	
Sound <input type="radio"/> FAIR · Attn	
Oil leakage <input type="radio"/> FAIR · Attn	
Power <input type="radio"/> FAIR · Attn	
COOLING SYSTEM	
Radiator <input type="radio"/> FAIR · Attn	
Oil Cooler <input type="radio"/> FAIR · Attn	
OPERATING SYSTEM	
Computer <input checked="" type="radio"/> OK · NG	
Swing <input type="radio"/> FAIR · Attn	
Travel <input type="radio"/> FAIR · Attn	
TRANSMISSION	
Transmission <input type="radio"/> FAIR · Attn	
No. OF GEARS	3 GEARS
No. of DRIVE WHEELS	4 WD
INTERIOR See Photos. 写真参照	
Operator's Seat <input type="radio"/> FAIR · Attn	
Inside Cover <input type="radio"/> FAIR · Attn	
Glasses <input type="radio"/> FAIR · Attn	
AirCon <input checked="" type="radio"/> A/C · H/C · H only · C only · None	
COMMENT	

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT <input type="radio"/> FAIR · Attn	
DERRICKING CYL. <input type="radio"/> FAIR · Attn	
EXTENSION CYL. <input type="radio"/> FAIR · Attn	
JIB	<input checked="" type="radio"/> YES · NO
JIB TYPE	STD · <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
HOOK	12t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5
COMMENT	
OUTRIGGERS	
OUTRIGGERS <input checked="" type="radio"/> X · H	
OUTRIGGERS COND. <input type="radio"/> FAIR · Attn	
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
5	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。