

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/2	MAKE	KOBELCO	MODEL	RK250-6
SERIAL No.	PLATE : EZ08-10317		STAMP : EZ08-10317		
HR METER	26725	HR	Odometer	56675	km
TIRE SIZE	385/95R25		YEAR	YR	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR <input type="radio"/> Attn <input checked="" type="radio"/> *1	
Blow-By	FAIR <input type="radio"/> Attn <input type="radio"/> A LITTLE · MIDDLE <input checked="" type="radio"/> SEVERE	
Sound	FAIR <input type="radio"/> Attn <input type="radio"/>	
Oil	FAIR <input type="radio"/> Attn <input type="radio"/>	
Exhaust Color	FAIR <input type="radio"/> Attn <input type="radio"/>	
<b>OPERATION PUMP</b>		
Sound	FAIR <input type="radio"/> Attn <input type="radio"/>	
Oil leakage	FAIR <input type="radio"/> Attn <input type="radio"/>	
Power	FAIR <input type="radio"/> Attn <input type="radio"/>	
<b>COOLING SYSTEM</b>		
Radiator	FAIR <input type="radio"/> Attn <input type="radio"/>	
Oil Cooler	FAIR <input type="radio"/> Attn <input type="radio"/>	
<b>OPERATING SYSTEM</b>		
Computer	OK <input checked="" type="radio"/> NG <input type="radio"/>	
Swing	FAIR <input type="radio"/> Attn <input type="radio"/>	
Travel	FAIR <input type="radio"/> Attn <input type="radio"/>	
<b>TRANSMISSION</b>		
Transmission	FAIR <input type="radio"/> Attn <input checked="" type="radio"/> *2	
No. OF GEARS	3 GEARS	
No. of DRIVE WHEELS	4 WD	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	FAIR <input type="radio"/> Attn <input type="radio"/> 破れあり HUGE CUTS	
Inside Cover	FAIR <input type="radio"/> Attn <input type="radio"/>	
Glasses	FAIR <input type="radio"/> Attn <input type="radio"/>	
AirCon	A/C <input checked="" type="radio"/> H/C <input type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None	
<b>COMMENT</b>		

<b>BOOM</b>	
No. of Section	4 SECTIONS
CRACK/ENFORCEMENT	FAIR <input type="radio"/> Attn <input type="radio"/>
DERRICKING CYL.	FAIR <input type="radio"/> Attn <input type="radio"/>
EXTENSION CYL.	FAIR <input type="radio"/> Attn <input type="radio"/>
JIB	YES <input checked="" type="radio"/> NO <input type="radio"/>
JIB TYPE	STD <input type="radio"/> PWR <input checked="" type="radio"/>
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO <input type="radio"/>
HOOK	25t, BALL
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
左F、右Rタイヤ摩耗大 FRONT LEFT & REAR RIGHT TIRES: MUCH WORN	
<b>OUTRIGGERS</b>	
OUTRIGGERS	X <input checked="" type="radio"/> H <input type="radio"/>
OUTRIGGERS COND.	FAIR <input type="radio"/> Attn <input type="radio"/>
<b>COMMENT</b>	
*1 E/Gヘッド付近にじみあり AROUND CYLINDER HEAD: OIL OOZING	
*2 ミッション付近にじみあり AROUND TRANSMISSION: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。