

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/2	MAKE	KATO	MODEL	KRM-25H
SERIAL No.	PLATE :	0612021		STAMP :	KR248-2021
HR METER	10227	HR	Odometer	144314	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL S/N

Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	A LITTLE <input checked="" type="radio"/> MIDDLE <input type="radio"/> SEVERE
Sound	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	
Oil	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	

OPERATION PUMP

Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	
Power	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	

COOLING SYSTEM

Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	

OPERATING SYSTEM

Computer	<input checked="" type="radio"/> OK	NG	
Swing	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	
Travel	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	

TRANSMISSION

Transmission	<input checked="" type="radio"/> FAIR	Attn	*1
No. OF GEARS	4	GEARS	
No. of DRIVE WHEELS	4	WD	

INTERIOR See Photos. 写真参照

Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	
Inside Cover	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	
Glasses	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	上部ガラスひび割れあり SKYLIGHT: CRACKED
AirCon	<input checked="" type="radio"/> A/C	<input type="radio"/> H/C	<input type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	
DERRICKING CYL.	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	
EXTENSION CYL.	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	
JIB	<input checked="" type="radio"/> YES	<input type="radio"/> NO	
JIB TYPE	<input type="radio"/> STD	<input checked="" type="radio"/> PWR	
MAIN & SUB WIRE	<input checked="" type="radio"/> YES	<input type="radio"/> NO	
HOOK	25t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
--	---

COMMENT

OUTRIGGERS

OUTRIGGERS	X	<input checked="" type="radio"/> H	
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR	<input type="radio"/> Attn	

COMMENT

サーチャフック付 W/SEARCHER HOOK
補巻ブレーキシリンダー油漏れあり
AUXILIARY HOISTING WINCH BRAKE CYLINDER: OIL LEAKING
主巻ウインチモーター、補巻ウインチモーター油漏れあり
MAIN & AUXILIARY HOISTING WINCH MOTORS: OIL LEAKING
*1 ミッション付近、トルコンエレメントホース油漏れあり
*1 AROUND TRANSMISSION & TORQUE CONVERTER FILTER HOSE: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。