

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/2	MAKE	KATO	MODEL	KR-10H-L II
SERIAL No.	PLATE :	3910079		STAMP :	KR102-0079
HR METER	23726	HR	Odometer	114709	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL	S/N
Oil leakage	<input type="radio"/> FAIR <input checked="" type="radio"/> Attn 下周り油漏れ大 BOTTOM: SEVERE OIL LEAKING
Blow-By	<input type="radio"/> FAIR <input checked="" type="radio"/> Attn A LITTLE <input checked="" type="radio"/> MIDDLE <input type="radio"/> SEVERE
Sound	<input type="radio"/> FAIR <input type="radio"/> Attn
Oil	<input type="radio"/> FAIR <input type="radio"/> Attn
Exhaust Color	<input type="radio"/> FAIR <input checked="" type="radio"/> Attn 白煙大 MUCH WHITE FUMES

OPERATION PUMP	
Sound	<input type="radio"/> FAIR <input type="radio"/> Attn
Oil leakage	<input type="radio"/> FAIR <input type="radio"/> Attn
Power	<input type="radio"/> FAIR <input type="radio"/> Attn

COOLING SYSTEM	
Radiator	<input type="radio"/> FAIR <input type="radio"/> Attn
Oil Cooler	<input type="radio"/> FAIR <input type="radio"/> Attn

OPERATING SYSTEM	
Computer	<input checked="" type="radio"/> OK <input type="radio"/> NG
Swing	<input type="radio"/> FAIR <input type="radio"/> Attn
Travel	<input type="radio"/> FAIR <input type="radio"/> Attn

TRANSMISSION	
Transmission	<input type="radio"/> FAIR <input type="radio"/> Attn
No. OF GEARS	4 GEARS
No. of DRIVE WHEELS	4 WD

INTERIOR See Photos. 写真参照	
Operator's Seat	<input type="radio"/> FAIR <input type="radio"/> Attn
Inside Cover	<input type="radio"/> FAIR <input type="radio"/> Attn
Glasses	<input type="radio"/> FAIR <input type="radio"/> Attn
AirCon	<input checked="" type="radio"/> A/C <input type="radio"/> H/C <input type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None

COMMENT	

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	<input type="radio"/> FAIR <input type="radio"/> Attn
DERRICKING CYL.	<input type="radio"/> FAIR <input type="radio"/> Attn
EXTENSION CYL.	<input type="radio"/> FAIR <input type="radio"/> Attn
JIB	<input checked="" type="radio"/> YES <input type="radio"/> NO
JIB TYPE	<input type="radio"/> STD <input type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES <input type="radio"/> NO
HOOK	10t, BALL

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

COMMENT	
リヤステ不良 REAR STEERING: MALFUNCTION	

OUTRIGGERS	
OUTRIGGERS	<input type="radio"/> X <input checked="" type="radio"/> H
OUTRIGGERS COND.	<input type="radio"/> FAIR <input type="radio"/> Attn

COMMENT	
ML画面映り悪い ML MONITOR: BLURRED	
オイルクーラーホース油漏れあり OIL COOLER HOSE: OIL LEAKING	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。