

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2024/4/1	MAKE	TOYOTA	MODEL	50-4FD120
SERIAL	4FD120-50013		STAMP	4FD120-50013	
HR METER	21909	HR	Odometer	38364	km
CAB/CNP	<input checked="" type="radio"/> CAB	<input type="radio"/> CNP	<input type="radio"/> NONE	TIRE SIZE	10.00-20
MAX LIFTING HEIGHT	3.0	m	<input checked="" type="radio"/> VIEW	MONO	FORK LENGTH
FORK SPEC	サイドシフト付 W/SIDE-SHIFT				

ENGINE : MODEL	S/N
Oil leakage <input checked="" type="radio"/> FAIR · Attn	
Blow-By <input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound <input checked="" type="radio"/> FAIR · Attn	
Oil <input checked="" type="radio"/> FAIR · Attn	
Exhaust Color <input checked="" type="radio"/> FAIR · Attn	
US EPA YES · <input checked="" type="radio"/> NO	
OPERATION PUMP	
Sound <input checked="" type="radio"/> FAIR · Attn	
Oil leakage <input checked="" type="radio"/> FAIR · Attn	
Power <input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM	
Radiator <input checked="" type="radio"/> FAIR · Attn	
Oil Cooler <input checked="" type="radio"/> FAIR · Attn	
TRANSMISSION & TRAVEL	
T/M TYPE <input checked="" type="radio"/> PS · DD	
Transmission <input checked="" type="radio"/> FAIR · Attn	
Travel <input checked="" type="radio"/> FAIR · Attn	
FOOT BRAKE <input checked="" type="radio"/> FAIR · Attn	
PARKING BRAKE <input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照	
Operator's Seat <input checked="" type="radio"/> FAIR · Attn	破れあり HUGE CUTS
Inside Cover <input checked="" type="radio"/> FAIR · Attn	
Glasses <input checked="" type="radio"/> FAIR · Attn	
AirCon <input checked="" type="radio"/> A/C · H/C · H only · C only · None	
HYDRAULICS	
MAST Cylinder <input checked="" type="radio"/> FAIR · Attn	
TILT Cylinder <input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。