

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/4/2	MAKE	KOMATSU	MODEL	PC138US-8
SERIAL	26437		STAMP	KMTPC189E01026437	
HR METER	9143	HR	YEAR	YR	
CAB/CNP	<input checked="" type="checkbox"/> ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL 4D95LE-5 S/N 519545

Oil leakage	<input checked="" type="checkbox"/> FAIR · Attn	
Blow-By	<input checked="" type="checkbox"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="checkbox"/> FAIR · Attn	
Oil	<input checked="" type="checkbox"/> FAIR · Attn	
Exhaust Color	<input checked="" type="checkbox"/> FAIR · Attn	
US EPA	<input checked="" type="checkbox"/> YES · NO	

MAIN PUMP

Sound	<input checked="" type="checkbox"/> FAIR · Attn	
Oil leakage	<input checked="" type="checkbox"/> FAIR · Attn	
Power	<input checked="" type="checkbox"/> FAIR · Attn	

COOLING SYSTEM

Radiator	<input checked="" type="checkbox"/> FAIR · Attn	
Oil Cooler	<input checked="" type="checkbox"/> FAIR · Attn	

OPERATING SYSTEM

Swing	<input checked="" type="checkbox"/> FAIR · Attn	ガタあり LOOSE
Travel	<input checked="" type="checkbox"/> FAIR · Attn	

INTERIOR See Photos. 写真参照

Operator's Seat	<input checked="" type="checkbox"/> FAIR · Attn	破れあり A LITTLE DAMAGED
Inside Cover	<input checked="" type="checkbox"/> FAIR · Attn	
Glasses	<input checked="" type="checkbox"/> FAIR · Attn	
AirCon	<input checked="" type="checkbox"/> A/C · H/C · H only · C only · None	

BOOM / ARM / BKT

Boom	<input checked="" type="checkbox"/> FAIR · Attn	
Boom Cylinder	<input checked="" type="checkbox"/> FAIR · Attn	
Arm	<input checked="" type="checkbox"/> FAIR · Attn	
Arm Cylinder	<input checked="" type="checkbox"/> FAIR · Attn	
BKT	<input checked="" type="checkbox"/> FAIR · Attn	ガタあり LOOSE
BKT Cylinder	<input checked="" type="checkbox"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

COMMENT

シューパッド摩耗大、剥がれ多数あり RUBBER PADS: ALMOST GONE

BKT	STD / SLOPE / NARROW	<input checked="" type="checkbox"/> SKELETON OTHER ()
Lever	LONG · <input checked="" type="checkbox"/> WRIST	
Multi	<input checked="" type="checkbox"/> MULTI · 2 · NO	
ARM-CRANE	YES · <input checked="" type="checkbox"/> NO	
BLADE	YES · <input checked="" type="checkbox"/> NO	
OFFSET	YES · <input checked="" type="checkbox"/> NO	
OFFSET Cylinder	FAIR · Attn	
Piping	<input checked="" type="checkbox"/> YES · NO	Breaker only · <input checked="" type="checkbox"/> Multi

COMMENT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。